

Document 2022 GW2694

Book 2022 Page 2694 Type 43 001 Pages 5 Date 9/12/2022 Time 11:59:31AM

Rec Amt \$.00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TR	•	AIC		^	~	
	4		 •		-	•

Name: Laura L. Stewart

Address: 3244 Deer Run Avenue, Lorimor, IA 50149

TRANSFEREE:

Name: Kevin Blair and Donna Blair

Address: 3244 Deer Run Avenue, Lorimor, IA 50149

Address of Property Transferred:

3244 Deer Run Avenue, Lorimor, Iowa 50149

Legal Description of Property: (Attach if necessary)

The South Half (1/2) of the Southwest Quarter (1/4) of the Northwest Quarter (1/4) of Section Twenty-seven (27), Township Seventy-four (74) North, Range Twenty-nine (29) West of the 5th P.M., Madison County, Iowa.

1. Wells (check one)

- ☐ There are no known wells situated on this property.
- There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- ☑ There is no known solid waste disposal site on this property.
- ☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☑ There is no known hazardous waste on this property.
- ☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☑ There are no known private burial sites on this property.
- ☐ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☐ All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)

×	There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be
	responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form. There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this
	form. There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to permit number
Informa hereto:	ation required by statements checked above should be provided here or on separate sheets attached
	The Well is located in the Southeast (SE) corner of the pasture approximately 50 feet from the east fence.
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Signatu	re: Laura L. Stewart Telephone No.: 515.360.3939



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information	
Current Owner LAURA STEWAR	<i></i>
Buyer KEVIN & DONNA BLAIR R	ealtor FOR SALE BY OWNER
Mailing Address 3244 DEER RUN AVE	LORIMOR, TA. 50149
Site Address/County 3244 DEER RUN	•
No. of Bedrooms 3 Last Occupied? CURRENT Dispos	al? YN Softener? YN H2O Supply? RURAL
Records Available YES Permit/Installation Date 6	-20-05 Installer MIKE HARKIN
Cautia Caratama Information	Cuminition, In.
Septic Tank(s): Size /250 Gaz. Material (ANCOFIF Condition COO
Tank Pumped? VES Date 7-19-22	Licensed Pumper 1/64 DOS PODE
Tank Pumped? YES Date 7-19-22 Septic/Trash/Processing Tank: Size Ma	aterial Condition
Tank pumped? Date	Licensed Pumper
A analysis transforment sport (ATID) ACCCD	O:
Aerobic treatment unit (ATU) MFGR Tank Pumped? Date	Size
Maintenance Contract? Expiration Date	Service Provider
Condition	Service Flovider
Pump Ttanks/Vaults: Type Size	Condition
Distribution System: Distribution Box VE3 Ou	otlets Used 4 Condition GRED
Header Pine(s) VE	Number of Lines 4
Pressure Dosed?	·
C	
Secondary Treatment Longth of Absorption Fields 95'	Determined by DODEC - COMARTY MAD
Length of Absorption Fields 95'	Determined by WYDORUM LOAD TEST
Condition of Fields WORKING Type of Trench Material CHAMBER 36	NO SURFACE DISCHARGE
Type of Trench Waterial CHANGE SE	700 GARTING CICETHING
Size of Sand Filter	Determined by
Vent Pipes Above Grade?	Discharge Pipe Located?
Effluent Sample Taken?	Results
-	
Media Filters: Type	
Maintenance Contract? Expiration Date	Service Provider
Condition	
NPDES General Permit No. 4: Required?	Permitted? NOI submitted

542-0191



Time of Transfer Inspection Worksheet

Alarms NA	Working?		disinfection NA	wasking?	
			• •		-
Control box	<u>A</u> Ti	mers NA	inspection ports	<u>NA</u>	
Other components					
Outer Components			And the second s		.
Overall condition of	f the private sewas	ze disposal system		•	
	_				•
Acceptable? YE	3,	-	Unacceptable?		<u>.</u>
Dunlain (attack add		adam Tanu	LIAZ ALMASA	4449 4 5057	0-5
			WAS PUMPED OX WAS EXP		RED
			MON-ALL 4		_
			AND NO BAC		-
			FION OF THE		
			THERE WAS L		
			FIER CONSTR		
			TO BE AFFE		e Function
Site status at coach	usion of Time of T	ransfer inspection:	AT THIS ?	TIME.	·. •
A/A 37	<u> </u>				
	ify that controls an ear is on to all com		eiric hings.		
	isit all components	- .		•	
	her all tools for rea				
	ify that no sewage				
	my man in initial	# ***			
Using this worksho	et, write a narrativ	e report of the ins	pection results.		•
Submit a copy of the	ris report, includia	g your namative, t	o the city/county cav	irenmental health	
office, the DNR an	d the county Reco	rder in the county	where the inspection	was conducted.	
				Latina of	(N.
This report indicat	s the condition of	the private sewag	e disposal system at t	HIS UNIS UL Ancilu	10th X
the inspection. It c	loes not Sastanace		e to function satisfac	many.	
Signature of Certif	ied inspector:	In Cornet	WCS	Date: July 2	K-2022
Name (print):	N CORNISM/L		L SERVICE (Certificate #: 20	<i>2</i> 7
Address: 10	20 130 th	DEXTER 2	A. 50070		<u> </u>
	515-249-9				•

