BK: 2022 PG: 3020

Recorded: 10/17/2022 at 2:19:35.0 PM

Pages 10

County Recording Fee: \$0.00 Iowa E-Filing Fee: \$0.00 Combined Fee: \$0.00

Revenue Tax:

LISA SMITH RECORDER Madison County, Iowa

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name: Bryson James Hall

Address: 1649 210th Street, Winterset, IA 50273

TRANSFEREE:

Name: IPE1031 REV442, LLC

Address: 6150 Village View Drive, Ste. 113, West Des Moines, Iowa 50266

Address of Property Transferred:

Bare land in Madison County, Winterset, Iowa 50273

Legal Description of Property: (Attach if necessary)

The Northeast Quarter (¾) of the Southwest Quarter (¾) of Section Thirty (30), Township Seventy-six (76) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, AND Parcel "A" located in the South Fractional Half (½) of the Northwest Quarter (¾) and in the Northwest Fractional Quarter (¾) of the Southwest Quarter (¾) of said Section Thirty (30), containing 43.24 acres, as shown in Amended Plat of Survey filed in Book 2008, Page 3113 on October 21, 2008, in the Office of the Recorder of Madison County, Iowa; EXCEPT that part of Parcel "E" located in the Southeast Quarter (¾) of the Northwest Quarter (¼), as shown in Plat of Survey filed in Book 2022, Page 759 on March 14, 2022, in the Office of the Recorder of Madison County, Iowa.

1. Wells (check one)

	There	are n	o known	wells	situated	on	this	proper	tv.
--	-------	-------	---------	-------	----------	----	------	--------	-----

X There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

X There is no known solid waste disposal site on	this	property
--	------	----------

☐ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

X There is no known hazardous waste on this property.

☐ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- X There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

X There are no known private burial sites on this property.

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)

☐ There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
6. Private Sewage Disposal System (check one)
☐ All buildings on this property are served by a public or semi-public sewage disposal system.
☐ This transaction does not involve the transfer of any building which has or is required by law to have a
sewage disposal system.
X There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
☐ There is a building served by private sewage disposal system on this property. Weather or other
temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
\square There is a building served by private sewage disposal system on this property. The buyer has executed a
binding acknowledgment with the county board of health to install a new private sewage disposal system
on this property within an agreed upon time period. A copy of the binding acknowledgment is provided
with this form.
☐ There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
☐ This property is exempt from the private sewage disposal inspection requirements pursuant to the
following exemption [Note: for exemption #9 use prior check box]:
☐ The private sewage disposal system has been installed within the past two years pursuant to permit
number
Information required by statements checked above should be provided here or on separate sheets attached hereto:
1. One (1) Well located approximately 100' west of the trailer.
I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS
FOR THIS FORM AND THAT THE INFORMATION STATED
ABOVE IS TRUE AND CORRECT.
Signature: Telephone No.: (515) 210-8040
(Transferor)

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 1642 JESSY HAKIZIMANA CERT # 12622

Site Information

Parcel Description: 30-T76N-R28W

Address: 1649 210th St, Winterset, IA 50273

County: Madison

Owner Information

Property is owned by a business: No

Business Name:

Owner Name: Bryce Hall

Email Address:

Address: 1649 210th St, Winterset, IA 50273

Phone No: 515-979-3057

Additional Contact Information

Name

Email Address

Affiliate Type

Daran Becker

Daran@peoplescompany.com

Realtor

Site related information

No Of Bedrooms: 2

Inspection Date: 12/03/2013

Facility Type: Residential

Currently Occupied: Yes

Last Occupied:

System Installation Date: 12/03/2013

Permit issued by County: Yes

Permit Number: 086-12

All plumbing fixtures enter septic system: Yes

County contacted for records: Yes

Property Information Comments:

Installation appears to be good and system is in good working condition

Primary Treatment

Tank 1

Tank Name: Tank 1

Type: Septic Tank

Tank Size (Gal): 1500

Tank Material: Concrete

Tank Corrosion Type: Slight

Liquid Level Type: Normal

No. of Compartments: 2

Pump Tank Chamber: No

Licensed Pumper Name: **Country side**

septic

Date Pumped: **8/15/2022**

Meets Setback to Well: N/A

Well Type:

Distance To Well (Ft.):

Is Accessible: Yes

Lid Intact: Yes

Risers Intact: No

Effluent Filter Present: Yes

Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

Tank Comments: Septic tank appears to be in good working condition.

General Primary Treatment Comments:

Distribution Type

Drop Box 1

Label: Drop Box 1

Material Type: Plastic

Accessible: Yes

Box Opened: Yes

Speed Levelers Present: Yes

Watertight: Yes

Functioning As Designed: Yes

General Distribution System Comments: Distribution box appears to be in good working condition. I ran 300 gallons of water and

took water no issues

Secondary Treatment

Lateral Field1

Lines: 4

Distribution Type: **Distribution Box**

Material Type: Rock and PVC Pipe

Total Length of Absorption Line: 200

System Hydraulic Loaded: Yes

Meets Setback to Well: N/A

Lateral Lines Probed: Yes

Saturation or Ponding Present: Yes

Well Type:

Trench Width: 14 inches

Lateral Lines Equal Length: Yes

System Located on Owner Property: Yes

Grass Cover Present: Yes Easement Present: N/A

Gallons Loaded: 300

Distance To Well (Ft.):

Functioning as Designed: Yes

Comments: I did prob the laterals and appears to working as designed. Distribution box appears to be working well and takes

water

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: Overall the system appears to be in good working condition. No issues



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS LT. GOVERNOR ADAM GREGG

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 1642 JESSY HAKIZIMANA CERT # 12622

Owner Name:

Bryce Hall

Address:

1649 210th St , Winterset , IA 50273

County:

Madison

Inspection Date:

12/03/2013

Submitted Date:

08/16/2022

This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).









