



Document 2023 GW601

Book 2023 Page 601 Type 43 001 Pages 6

Date 3/24/2023 Time 1:58:54PM

Rec Amt \$.00

INDX  
ANNO  
SCAN

BRANDY MACUMBER, COUNTY RECORDER  
MADISON COUNTY IOWA

CHEK

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT  
TO BE COMPLETED BY TRANSFEROR**

**TRANSFEROR:**

Name: Betty Vasey  
Address: 216 E. Green, Winterset, IA 50273

**TRANSFeree:**

Name: Loft Investments, LLC  
Address: 1716 Nuthatch Avenue, Afton, IA 50830

Address of Property Transferred:  
2450 Highway 169, Winterset, Iowa 50273

Legal Description of Property: (Attach if necessary)

Parcel "A" located in the Southwest Quarter (1/4) of the Northeast Quarter (1/4) of Section Fourteen (14), Township Seventy-five (75) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, containing 3.372 acres, as shown in Plat of Survey filed in Book 3, Page 89 on August 12, 1997, in the Office of the Recorder of Madison County, Iowa.

**1. Wells (check one)**

- No Condition - There are no known wells situated on this property.
- Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

**2. Solid Waste Disposal (check one)**

- No Condition - There is no known solid waste disposal site on this property.
- Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

**3. Hazardous Wastes (check one)**

- No Condition - There is no known hazardous waste on this property.
- Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

**4. Underground Storage Tanks (check one)**

- No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

**5. Private Burial Site (check one)**

- No Condition - There are no known private burial sites on this property.
- Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

**6. Private Sewage Disposal System (check one)**

- No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for exemption #7 use prior check box]:
- Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number:

\_\_\_\_\_

**Information required by statements checked above should be provided here or on separate sheets attached hereto:**

1 Well South of the driveway that's in front of the garage and has a white fence/enclosure around it.

**I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.**

Signature: Betty Vasquez Telephone No.: (515) 729-9182  
(Transferor)



**TIME OF TRANSFER INSPECTION TOT# 3918 ALLEN AKERS CERT # 1023**

Site Information

Parcel Description: **Parcel A 3.37 Acres SW NE**

Address: **2450 State Hwy 169, Winterset, IA 50273**

County: **Madison**

Owner Information

Property is owned by a business: **No**

Business Name:

Owner Name: **Betty Vasey**

Email Address:

Address: **216 E Green, Winterset, IA 50273**

Phone No: **515-729-9182**

Additional Contact Information

Name	Email Address	Affiliate Type
<b>Nick &amp; Dillon Roberts</b>		<b>Buyer</b>
<b>Toni Tindle</b>	<b>toni@coveredbridgerealtyinc.com</b>	<b>Realtor</b>

Site related information

No Of Bedrooms: **3**

Inspection Date: **02/09/2023**

Facility Type: **Residential**

Currently Occupied: **Yes**

Last Occupied:

System Installation Date: **10/21/1997**

Permit issued by County: **Yes**

Permit Number: **1623**

All plumbing fixtures enter septic system: **Yes**

County contacted for records: **Yes**

Property Information Comments:

Primary Treatment

**Norwesco**

Tank Name: **Norwesco**

Type: **Septic Tank**

Tank Size (Gal): **1000**

Tank Material: **Plastic**

Tank Corrosion Type: **None**

Liquid Level Type: **Normal**

No. of Compartments: **2**

Pump Tank Chamber: **No**

Licensed Pumper Name: **Weigert**

Date Pumped: **2/8/2023**

Meets Setback to Well: **N/A**

Well Type:

Distance To Well (Ft):

Is Accessible: **Yes**

Lid Intact: **Yes**

Risers Intact: **Yes**

Effluent Filter Present: **No**

Watertight: **Yes**

Tank/Vault Pumped: **Yes**

Inlet Baffle Present: **Yes**

Outlet Baffle Present: **Yes**

Functioning as Designed: **Yes**

Tank Comments:

General Primary Treatment Comments:

#### Distribution Type

##### **Distribution Box 1**

Label: **Distribution Box 1**

Material Type: **Plastic and Concrete**

Accessible: **Yes**

Box Opened: **Yes**

Baffle Present: **Yes**

Speed Levelers Present: **Yes**

Watertight: **Yes**

Functioning As Designed: **Yes**

General Distribution System Comments :

#### Secondary Treatment

##### **Lateral Field1 10" gravelless**

Distribution Type: **Distribution Box**

Material Type: **Gravelless Pipe**

Trench Width: **24**

Lines: **3**

Total Length of Absorption Line: **300**

System Hydraulic Loaded: **Yes**

Gallons Loaded: **400**

Meets Setback to Well: **N/A**

Well Type:

Distance To Well (Ft):

Lateral Lines Probed: **Yes**

Saturation or Ponding Present: **No**

Grass Cover Present: **Yes**

Lateral Lines Equal Length: **Yes**

System Located on Owner Property: **Yes**

Easement Present: **N/A**

Functioning as Designed: **Yes**

Comments:

General Secondary Treatment Comments:

#### Narrative Report

TOT Inspection Report Overall Narrative Comments: **Everything looks good at this time. Plastic tank w/riser to the top of the grou**



**TIME OF TRANSFER INSPECTION TOT# 3918 ALLEN AKERS CERT # 1023**


Owner Name: **Betty Vasey**

Address: **2450 State Hwy 169 , Winterset , IA 50273**

County: **Madison**

Inspection Date: **02/09/2023**

Submitted Date: **2/15/2023**



MAY 1999

GARY & DONNA JACOBS -  
 C&L CONST. - 10/21/97  
 Inspected: 10/22/97  
 Jerry K. Dravilbyan

1000 GALLON NORWESCO TANK  
 DIST. BOX