BK: 2024 PG: 1894

Recorded: 8/6/2024 at 2:33:32.0 PM

Pages 6

County Recording Fee: \$0.00 lowa E-Filing Fee: \$0.00 Combined Fee: \$0.00 Revenue Tax: \$0.00

BRANDY L. MACUMBER, RECORDER

Madison County, Iowa

# REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

TR	٨	MC	2	D	$\sim$	0	

Name: Ryan Florer and Sonja Florer Address: 2331 152nd Street, Winterset, IA

#### TRANSFEREE:

Name: Joe Paterno and Audrey Paterno

Address: 2331 152nd Street, Winterset, IA 50273

#### Address of Property Transferred:

2331 152nd Street, Winterset, Iowa 50273

#### Legal Description of Property: (Attach if necessary)

Lots Five (5), Six (6) and the East 141.2 feet of Lot Eight (8) of the Final Plat of Berglund Rural Estates Sub-District in the Northwest Quarter (1/4) of Section Thirty-two (32), in Township Seventy-seven (77) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa, EXCEPT all that Portion of Lot Five (5) lying North of the following described line: Beginning at a point on the East line of said Lot Five (5), 100 feet South of the Northeast Corner of said Lot Five (5), thence Westerly on a bearing of South 81° 43' West, a distance of 465.7 feet to the Southeast Corner of Lot Seven (7), being a point on the West line of said Lot Five (5).

#### 1 Wells (check one)

No Condition - There are no known wells situated on this p	property	١.
--	----------	----

Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

#### 2. Solid Waste Disposal (check one)

<b>☑</b>	No Condition - There is no known solid waste disposal site on this property.
	Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in
	Attachment #1, attached to this document.

### 3. Hazardous Wastes (check one)

NO Condition - There is no known hazardous waste on this property.
Condition Present - There is hazardous waste on this property and information related thereto is provided in
Attachment #1, attached to this document.

#### 4. Underground Storage Tanks (check one)

No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and
residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)

Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

	ite Burial Site (check one)
$oldsymbol{\square}$	No Condition - There are no known private burial sites on this property.
	Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying
	information of the decedent(s) is stated below or on an attached separate sheet, as necessary.
6. Priva	nte Sewage Disposal System (check one)
	No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
	No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a
	sewage disposal system.
	Condition Present - There is a building served by private sewage disposal system on this property or a building without
	any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the
	private sewage disposal system and whether any modifications are required to conform to standards adopted by the
_	Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
	Condition Present - There is a building served by private sewage disposal system on this property. Weather or other
	temporary physical conditions prevent the certified inspection of the private sewage disposal system from being
	conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified
	inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required
	modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
	Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to
	ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding
	acknowledgment with the county board of health to install a new private sewage disposal system on this property
	within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
	Condition Present - There is a building served by private sewage disposal system on this property. The building to which
	the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding
	acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of
	the binding acknowledgment is provided with this form. [Exemption #7]
	Condition Present - There is a building served by private sewage disposal system on this property. This property is
	exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for
	exemption #7 use prior check box]:
	<del></del>
	Condition Present - There is a building served by private sewage disposal system on this property. The private sewage
_	disposal system has been installed within the past two years pursuant to permit number:
	ation and the statement about above should be provided been or on conserts cheets attached bestor
The	ation required by statements checked above should be provided here or on separate sheets attached hereto:    Well is located sto from the house.
1116	SF SF
<del></del>	
	·
	DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED
ABOVE IS	5 TRUE AND CORRECT.
Cianatura	: (SMA ALRE) Telephone No.: (515) 669-0907
Signature	(Transferor)



### TIME OF TRANSFER INSPECTION TOT# 11248 BEN BEDWELL CERT # 11612

-Site Information -

Parcel Description: 150023248030000

Address: 2331 152nd st, Winterset, IA 50273

County: Madison

Owner Information

Property is owned by a business: No

**Business Name:** 

Owner Name: Sonja florer

**Email Address:** 

Address: 2331 152nd ave, Winterset, IA 50273

Phone No:

Additional Contact Information

-Site related information -

No Of Bedrooms: 3

Facility Type: Residential

**Last Occupied:** 

Permit issued by County: No

All plumbing fixtures enter septic system: Yes

**Property Information Comments:** 

Inspection Date: 07/03/2024

Currently Occupied: Yes

System Installation Date:

Permit Number:

County contacted for records: Yes

Primary Treatment

Tank 1

Tank Name: Tank 1

Tank Material: Concrete

No. of Compartments: 2

Date Pumped: 7/3/2024

Type: Septic Tank

Tank Corrosion Type: None

Pump Tank Chamber: No

Meets Setback to Well: N/A

Tank Size (Gal): 1000

Liquid Level Type: Normal

Licensed Pumper Name: weigert

Well Type:

Distance To Well (Ft.):

Is Accessible: Yes

Lid Intact: Yes

Risers Intact: Yes

Effluent Filter Present: Yes

Watertight: Yes

Tank/Vault Pumped: Yes

Inlet Baffle Present: Yes

Outlet Baffle Present: Yes

Functioning as Designed: Yes

**Tank Comments:** 

**General Primary Treatment Comments:** 

Distribution Type

**Distribution Box 1** 

Label: Distribution Box 1

Box Opened: Yes

Watertight: Yes

Material Type: Plastic

Baffle Present: Yes

Functioning As Designed: Yes

Accessible: **Yes** 

Speed Levelers Present: **Yes** 

**General Distribution System Comments:** 

Secondary Treatment

**Lateral Field1** 

Distribution Type: **Distribution Box** 

Lines: 5

Gallons Loaded: **250**Distance To Well (Ft.):

Grass Cover Present: **Yes** 

Easement Present: N/A

Comments:

Material Type: Rock and PVC Pipe

Total Length of Absorption Line: **500** 

Meets Setback to Well: N/A

Lateral Lines Probed: Yes

Lateral Lines Equal Length: Yes

Functioning as Designed: Yes

Trench Width: 24

System Hydraulic Loaded: Yes

Well Type:

Saturation or Ponding Present: No

System Located on Owner Property: Yes

**General Secondary Treatment Comments:** 

Narrative Report

TOT Inspection Report Overall Narrative Comments: The system was working properly during the Inspection.

**DIRECTOR KAYLA LYON** 

## TIME OF TRANSFER INSPECTION TOT# 11248 BEN BEDWELL CERT # 11612

Owner Name:

Sonja florer

Address:

2331 152nd st , Winterset , IA 50273

County:

**Madison** 

Inspection Date:

07/03/2024

**Submitted Date:** 

7/25/2024

