

806 Wyoming Ave., Creston, Iowa 50801 Phone: (641)782-4005

 Δ

A diagram showing a survey corner. A vertical line and a horizontal line intersect at a point marked with an 'X'. The vertical line is labeled "FENCE RUNNING NORTH IS ON THE GROUND" at the top. The horizontal line is labeled "FENCE RUNNING EAST-WEST IS UPRIGHT" at the right. Three trees are represented by circles with an 'X' inside:

- Top-left: "(S) FACE 14" OAK." with a dashed line to the corner intersection. The distance from the intersection to the tree is labeled "21.79'".
- Top-right: "(W) FACE 6" HICKORY." with a dashed line to the corner intersection. The distance from the intersection to the tree is labeled "13.77'".
- Bottom: "(N) FACE 24" OAK." with a dashed line to the corner intersection. The distance from the intersection to the tree is labeled "2.98'".

 The corner intersection is marked with an 'X' and a small triangle.

The seal is circular with a double-lined border. The outer ring contains the text "PROFESSIONAL LAND SURVEYOR" at the top and "IOWA" at the bottom, separated by two five-pointed stars. The center of the seal features the name "JOSHUA E. SCHNEIDER" in a bold, sans-serif font, with the number "24655" printed directly below it.

SURVEY FOR: FARMERS-COLLINS
DATE: 11-18-25
PROJECT NO. 6025851