



Document 2025 GW1270

Book 2025 Page 1270 Type 43 001 Pages 5
Date 5/23/2025 Time 1:44:03PM
Rec Amt \$.00

INDX
ANNO
SCAN

BRANDY MACUMBER, COUNTY RECORDER
MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name: Frank Thomas Lake
Address: 3052 Ivy Trail, Lorimor, IA 50149

TRANSFeree:

Name: Marty W. Kerns and Katy J. Kerns
Address: 22708 W. 182nd Street, Eagleville, MO 64442

Address of Property Transferred:
3052 Ivy Trail, Lorimor, Iowa 50149

Legal Description of Property: (Attach if necessary)

Parcel "A" located in the Northeast Quarter (NE 1/4) of the Southwest Quarter (SW 1/4) of Section Sixteen (16), Township Seventy-four (74) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, containing 8.508 acres, as shown in Amended Plat of Survey filed in Book 3, Page 421, on April 22, 1999, in the Office of the Recorder of Madison County, Iowa.

1. Wells (check one)

- ☐ No Condition - There are no known wells situated on this property.
- ☒ Condition Present - There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary. *NW corner of property, inactive*

2. Solid Waste Disposal (check one)

- ☒ No Condition - There is no known solid waste disposal site on this property.
- ☐ Condition Present - There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- ☒ No Condition - There is no known hazardous waste on this property.
- ☐ Condition Present - There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- ☒ No Condition - There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- ☐ Condition Present - There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)

- ☒ No Condition - There are no known private burial sites on this property.
- ☐ Condition Present - There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

6. Private Sewage Disposal System (check one)

- ☐ No Condition - All buildings on this property are served by a public or semi-public sewage disposal system.
- ☐ No Condition - This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- ☒ Condition Present - There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The system is failing to ensure effective wastewater treatment or is otherwise improperly functioning, and the buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #7]
- ☐ Condition Present - There is a building served by private sewage disposal system on this property. This property is exempt from the private sewage disposal inspection requirements pursuant to the following Exemption [Note: for exemption #7 use prior check box]:

- ☐ Condition Present - There is a building served by private sewage disposal system on this property. The private sewage disposal system has been installed within the past two years pursuant to permit number:

Information required by statements checked above should be provided here or on separate sheets attached hereto:

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature: _____

(Transferor)

Telephone No.: 515-505-4728



IOWA DEPARTMENT OF NATURAL RESOURCES

GOVERNOR KIM REYNOLDS
LT. GOVERNOR CHRIS COURNOYER

DIRECTOR KAYLA LYON

TIME OF TRANSFER INSPECTION TOT# 14009 SETH BROWN CERT # 13190

Site Information

Parcel Description: **660141662021000**

Address: **3052 Ivy Trail, Lorimor, IA 50149**

County: **Madison**

Owner Information

Property is owned by a business: **No**

Business Name:

Owner Name: **Frank Lake**

Email Address: **ftl19852005@gmail.com**

Address: **3052 Ivy Trail, Lorimor, IA 50149**

Phone No: **515-505-4728**

Site related information

No Of Bedrooms: **4**

Inspection Date: **02/27/2025**

Facility Type: **Residential**

Currently Occupied: **Yes**

Last Occupied:

System Installation Date: **07/13/2017**

Permit issued by County: **Yes**

Permit Number: **055-17**

All plumbing fixtures enter septic system: **Yes**

County contacted for records: **Yes**

Property Information Comments:

FSBO

Primary Treatment

Tank 1

Tank Name: **Tank 1**

Type: **Septic Tank**

Tank Size (Gal): **1500**

Tank Material: **Concrete**

Tank Corrosion Type: **Slight**

Liquid Level Type: **Normal**

No. of Compartments: **2**

Pump Tank Chamber: **No**

Licensed Pumper Name: **Rogers Septic**

Date Pumped: **2/27/2025**

Meets Setback to Well: **N/A**

Well Type:

Distance To Well (Ft.):

Is Accessible: **Yes**

Lid Intact: **Yes**

Risers Intact: **Yes**

Effluent Filter Present: **Yes**

Watertight: **Yes**

Tank/Vault Pumped: **Yes** Inlet Baffle Present: **Yes** Outlet Baffle Present: **Yes** Functioning as Designed: **Yes**

Tank Comments:

General Primary Treatment Comments:

Distribution Type

Distribution Box 1

Label: **Distribution Box 1**

Material Type: **Plastic**

Accessible: **Yes**

Box Opened: **Yes**

Baffle Present: **Yes**

Speed Levelers Present: **Yes**

Watertight: **Yes**

Functioning As Designed: **Yes**

General Distribution System Comments :

Secondary Treatment

Sand Filter1

Filter Type: **Subsurface**

Distribution Type: **Distribution Box**

Material Type: **Rock and PVC Pipe**

Absorption Area: **720**

System Hydraulic Loaded: **Yes**

Gallons Loaded: **300**

Discharge At Time of Inspection: **Yes**

CBOD5 Results: **8**

TSS Results: **4**

Disinfection Present: **No**

Disinfection Type:

Tertiary Treatment Present: **No**

Tertiary Treatment Type:

Meets Setback to Well: **N/A**

Well Type:

Distance To Well (Ft.):

Sand Filter Probed: **Yes**

Vent(s) Located: **Yes**

Saturation or Ponding Present: **No**

Grass Cover Over System: **Yes**

Outlet Found: **Yes**

Sample Taken: **Yes**

GP4 Permitted:

GP4 Required:

System Located on Owner Property: **Yes**

Easement Present: **N/A**

Functioning as Designed: **Yes**

Comments:

General Secondary Treatment Comments:

Narrative Report

TOT Inspection Report Overall Narrative Comments: **All wastewater goes to septic. 1500 gallon watertight concrete septic tank in working condition with slight deterioration. Accessible by inlet and outlet risers and lids to ground surface. Inlet and outlet baffles present, outlet filter present. Plastic watertight distribution box in working condition. Baffle and speed levelers present. 6 headers go out over sand filter. 18x40 equaling 720 sq ft subsurface sand filter in working condition. Vent pipe present. Hydraulic load tested(via house) and all headers took water. No frost/snow over sand filter. Sand filter probed dry and clean. Discharge pipe located, WATER SAMPLE COLLECTED.**

TIME OF TRANSFER INSPECTION TOT# 14009 SETH BROWN CERT # 13190

Owner Name: **Frank Lake**

Address: **3052 Ivy Trail , Lorimor , IA 50149**

County: **Madison**

Inspection Date: **02/27/2025**

Submitted Date: **3/13/2025**

This page certifies a Time of Transfer inspection was conducted and submitted for the property listed above in accordance with Subrule 567 IAC 69.2(8).