

Document 2009 GW3585

Book 2009 Page 3585 Type 43 001 Pages 6 Date 11/25/2009 Time 1:59 PM

Rec Amt \$.00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY 10WA

CHEK

### **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**

TO BE COMPLETED BY TRANSFEROR

TRANSFEROR: Name_Linda J. Kirkland			
Address 2346 St. Charles Rd.	Winterset	IA	50273
Number and Street or RR	City, Town or P.O.	State	Zip
TRANSFEREE:			
Name Rick A. Vert			
Address			
Number and Street or RR	City, Town or P.O.	State	Zip
Address of Property Transferred:			
2346 St. Charles Rd.	Winterset	IA	50273
Number and Street or RR	City, Town, or P.O.	State	e Zip
<ul> <li>There is a well or wells situated or stated below or set forth on an att</li> <li>Solid Waste Disposal (check one)</li> <li>There is no known solid waste disposal site</li> </ul>	ached separate sheet, as neces	ssary.	
Attachment #1, attached to this do		n related therett	o is provid <del>e</del> d
3. Hazardous Wastes (check one)			
There is no known hazardous was		Alexander de la	
<ul> <li>There is hazardous waste on this Attachment #1, attached to this do</li> </ul>		thereto is provid	ded in
4. Underground Storage Tanks (check			
There are no known underground small farm and residential motor f instructions.)	storage tanks on this property.		
<ul> <li>There is an underground storage t substance(s) contained are listed</li> </ul>			

Ͻ.	Ein	vate burial Site (Check One)
	X.	There are no known private burial sites on this property.
		There is a private burial site on this property. The location(s) of the site(s) and known
		identifying information of the decedent(s) is stated below or on an attached separate sheet, as
		necessary.
6.	Priv	vate Sewage Disposal System (check one)
		There are no known private sewage disposal systems on this property.
		There is a private sewage disposal system on this property. A certified inspector's report is
		attached which documents the condition of the private sewage disposal system and whether
		any modifications are required to conform to standards adopted by the Department of Natural
		Resources. A certified inspection report must be accompanied by this form when recording.
		There is a private sewage disposal system on this property. Weather or other temporary
		physical conditions prevent the certified inspection of the private sewage disposal system from
		being conducted. The buyer has executed a binding acknowledgment with the county board of
		health to conduct a certified inspection of the private sewage disposal system at the earliest
		practicable time and to be responsible for any required modifications to the private sewage
		disposal system as identified by the certified inspection. A copy of the binding acknowledgment
		is attached to this form. When the inspection is completed, an amended Groundwater Hazard
		Statement shall be recorded with the certified inspection and shall include the document
		numbers of both the real estate transfer document and the original Groundwater Hazard
		Statement.
		There is a private sewage disposal system on this property. The building to which the sewage
		disposal system is connected will be demolished without being occupied. The buyer has
		executed a binding acknowledgment with the county board of health to demolish the building
		within an agreed upon time period. A copy of the binding acknowledgment is provided with this
		form.
		This property is exempt from the private sewage disposal inspection requirements pursuant to
		the following exemption:
		The private sewage disposal system has been installed within the past two years pursuant to
		permit number
		·
Inf	orm	ation required by statements checked above should be provided here or on separate
sh	eets	attached hereto:
		in hont of the house underneath the green
	.00	ati Vid D
	12	$\omega_{0}\omega_{0}$
	•	
		<del></del>
		I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS
		FORM
		AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Sic	ınatı	ure: Telephone No.: (515)720-5/34
ی، د	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	(Transferor or Agent)

A parcel of land described as commencing at the Southwest corner of the Northeast Quarter (1/4) of Section Eight (8), in Township Seventy-five (75) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa, thence South 89°47′ East 1,094.07 feet along the South line of said Northeast Quarter (1/4) to centerline of a county road, thence North 13°20′ West 272.46 feet to point of beginning, thence North 13°20′ West 209.66 feet, thence Northwesterly 208.57 feet along a 818.60 foot radius curve concave Southwesterly having 208.03 feet long chord bearing North 20°38′ West, thence South 62°04′ West 170 feet, thence South 8°50′ West 170.13 feet, thence South 13°13′ East 279.30 feet, thence North 62°41′ East 263.50 feet to point of beginning, containing 2.3228 acres including 0.9595 Acres of county road right-of-way.



# **Time of Transfer Inspection Report**

**Property Information** 

Current Owner: Linda Kirkland					
Buyer: Rick Vert Realtor: Ryan Matthews					
Mailing Address: 1220 SE Waddel Way 1220 SE Waddel Way Waukee IA 50263					
Site Address/County: 2346 St Charles Rd Winterset IA 50273					
Legal Description					
No. of bedrooms: Last occupied: Current 5/09 Records available: yes					
Permit/ installation date: 066-07 9/4/07 Separation distances (ok/no?):					
Septic System Information					
Septic tank(s): Size: 1500 AK Material: Plastic Condition: Good					
Tank pumped?  Y N Date: Licensed pumper:					
Septic/Trash/Processing tank: Size: Material: Condition:					
Tank pumped?					
Aerobic treatment unit (ATU) mfgr Size					
Tank pumped?  Y N Date: Licensed pumper:					
Maintenance contract?					
Condition:					
Pump tanks/vaults: Type: Size: Condition:					
Distribution system: Distribution box Outlets used Condition:					
Header pipe(s): No. of lines: Pressure dosed?					
Secondary Treatment:					
Length of absorption fields: Determined by:					
Condition of fields: Determined by:					
Type of trench material:					
Size of sand filter: Determined by:					
Vent pipes above grade?					
Effluent sample taken Results:					
Media Filters: Type: Peat Moss/ Eco-Pure					
Golightly Const  Maintenance contract?					
Condition: Tank is in good condition					



NPDES General Permit No. 4:	Required?	☐ Y ☐ N	Permitted?	☐ Y ☐ N	NOI provided:

## Time of Transfer Inspection Report

Other components:					
Alarms: YNN	Working: Y N	Disinfection: Y N	Working: YNN		
Control Box:	Timers:	Inspection Ports:			
Other components:					
Overall condition of the	e private sewage disposal syste	m:			
Report system status:					
Explain (attach addition	nal pages as needed):				
Comments:					
Site status at conclusion	of Time of Transfer inspectio	on:			
Verify that controls are set on the appropriate mode.					
<ul> <li>Power is on to all components.</li> <li>Revisit all components to verify lids are secure.</li> </ul>					
<ul> <li>Gather all tools for removal from the site.</li> <li>Verify that no sewage is on the ground surface.</li> </ul>					
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.					
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.					
Signature of Certified Ir	nspector: MY	Date:	11/13/09		
Name (print):	tin mely	Certificate #:	9031		
Address: Golightly C	Construction Inc Po Box 36	Earlham IA 50072			
Phone #: 515-758-39	26				
<del>-</del> -	•	sketch to the seller/agent, buyer/a ie inspection was conducted, the conducted is the conducted in the conducted in the conducted is the conducted in the conducted in the conducted is the conducted in the condu	•		

Iowa DNR Onsite Wastewater Program

### **GOLIGHTLY CONSTRUCTION INC**

Po Box 36 Earlham, IA 50072 Ph: 515-758-3926 Fax: 515-758-3860

#### SEPTIC SYSTEM EVALUATION REPORT

DATE: 11/13/09

RE: 2346 St Charles Rd Winterset IA 50273

At the time of this inspection this system is in good condition.

Tanks are in good condition. Sludge level is 6 inches. This system does not need pumped, it is just now working good.

Tank has one foot risers and outlet pipe is free of debris and in good condition.

Should there be any questions regarding this report please contact our office.

Thank you Golightly Construction