



Document 2010 GW2076

Book 2010 Page 2076 Type 43 001 Pages 4

Date 9/01/2010 Time 10:55 AM

Rec Amt \$.00

INDX  
ANNO  
SCAN  
CHEK

LISA SMITH, COUNTY RECORDER  
MADISON COUNTY IOWA

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**  
TO BE COMPLETED BY TRANSFEROR

**TRANSFEROR:**

Name BETTY J. KIRKLAND TRUS

Address 83 Mark Twain Drive, Branson West, MO 65737

Number and Street or RR

City, Town or P.O.

State

Zip

**TRANSFeree:**

Name W. Wayne Young and Jo Young

Address 1571 - 210th Street, Winterset, IA 50273

Number and Street or RR

City, Town, or P.O.

State

Zip

Address of Property Transferred:

2009 North John Wayne Drive, Winterset, IA 50273

Number and Street or RR

City, Town, or P.O.

State

Zip

Legal Description of Property: (Attach if necessary)

An undivided one-half interest in and to:

Lot Nine (9) of C & C Allen's Addition to the City of Winterset, Madison County, Iowa.

**1. Wells (check one)**

- There are no known wells situated on this property.
- There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

**2. Solid Waste Disposal (check one)**

- There is no known solid waste disposal site on this property.
- There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

**3. Hazardous Wastes (check one)**

- There is no known hazardous waste on this property.
- There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

**4. Underground Storage Tanks (check one)**

- There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

**5. Private Burial Site (check one)**

- There are no known private burial sites on this property.
- There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

**6. Private Sewage Disposal System (check one)**

- All buildings on this property are served by a public or semi-public sewage disposal system.
- This transaction does not involve the transfer of any building.
- There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
- This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: \_\_\_\_\_.
- The private sewage disposal system has been installed within the past two years pursuant to permit number \_\_\_\_\_.

**Information required by statements checked above should be provided here or on separate sheets attached hereto:**

---



---



---



---

**I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.**

Signature: *Betty J. Kirkland* Telephone No.: (515) 462-4928  
(Transferor or Agent)



*Buyers Copy*

Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner Beggs Betty K Ireland  
Buyer Mason Back Realtor Covered Bridge Realty - Winterset, Mo  
Mailing address 1571 E 210 St - Winterset, Mo  
Site Address/County 2009 N. John Wayne Drive Winterset, Mo. Madison  
Legal Description \_\_\_\_\_

No. of bedrooms 3 Last occupied? in now Records available yes  
Permit/installation date 12-22-01 Separation distances ok/ no? OK  
L-#2064

Septic system information

Septic tank(s): size 1500 gal. material concrete condition good  
Tank pumped? yes date 7-6-10 licensed pumper Mason ST. 75  
Septic/trash/processing tank: size \_\_\_\_\_ material \_\_\_\_\_ condition \_\_\_\_\_  
Tank pumped? \_\_\_\_\_ date \_\_\_\_\_ licensed pumper \_\_\_\_\_

Aerobic treatment unit (ATU) mfg \_\_\_\_\_ size \_\_\_\_\_  
Tank pumped? \_\_\_\_\_ date \_\_\_\_\_ licensed pumper \_\_\_\_\_  
Maintenance contract? \_\_\_\_\_ expiration date \_\_\_\_\_ service provider \_\_\_\_\_  
Condition \_\_\_\_\_

Pump tanks/vaults: type \_\_\_\_\_ size \_\_\_\_\_ condition \_\_\_\_\_

Distribution system: distribution box Plastic outlets used 3 condition good  
Header pipe(s) 2 # of lines 3 Pressure dosed? no

Secondary treatment:  
length of absorption fields 100' determined by walking & probing  
condition of fields good determined by walking & probing  
type of trench material Chamber

Size of sand filter \_\_\_\_\_ determined by \_\_\_\_\_  
Vent pipes above grade? \_\_\_\_\_ discharge pipe located? \_\_\_\_\_  
Effluent sample taken? \_\_\_\_\_ Results \_\_\_\_\_

Media filters: type \_\_\_\_\_  
Maintenance contract? \_\_\_\_\_ expiration date \_\_\_\_\_ service provider \_\_\_\_\_  
Condition \_\_\_\_\_

NPDES General Permit No. 4: required? \_\_\_\_\_ permitted? \_\_\_\_\_ NOI provided \_\_\_\_\_

*Mason Back*



### Time of Transfer Inspection Report

Other components:

Alarms \_\_\_\_\_ Working? \_\_\_\_\_ disinfection \_\_\_\_\_ working? \_\_\_\_\_

Control box \_\_\_\_\_ Timers \_\_\_\_\_ inspection ports \_\_\_\_\_

Other components \_\_\_\_\_

Overall condition of the private sewage disposal system

Report system status The septic system at 2009 N. John Wayne Dr. is in very good cond. at 7-6-10

Explain (attach additional pages as needed): The septic tank was opened & cleaned on 7-6-10 by Mayer - S.T. 75 - the tank contents divider is in place & intake & outflow baffles are in place & good cond. Water was seen into system the day of inspect. & lateral field was taking water & no water was coming to surface on lateral field.

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode. to septic tanks
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface. None

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: John W. Mayer Date: 7-6-10  
 Name (print): JOHN MAYER Certificate #: 8979  
 Address: SEPTIC TANK PUMPING  
 Phone #: 515-462-2624 1509 St. Hwy. 92  
Winterset, IA 50273-8411

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;

Iowa DNR Onsite Wastewater Program  
502 E. 9<sup>th</sup> St.  
Des Moines, IA 50319

Picture on Back →