



Document 2010 GW2707

Book 2010 Page 2707 Type 43 001 Pages 5

Date 10/29/2010 Time 4:20 PM

Rec Amt \$.00

INDX ✓  
ANNO ✓  
SCAN ✓  
CHEK ✓

LISA SMITH, COUNTY RECORDER  
MADISON COUNTY IOWA

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT  
TO BE COMPLETED BY TRANSFEROR**

**TRANSFEROR:**

Name Randal J. Jordan and Radena J. Jordan

Address 2912 Cedar Bridge Road, Winterset, IA 50273

Number and Street or RR

City, Town or P.O.

State

Zip

**TRANSFeree:**

Name Jerry L. Nichols, Lonnie L. Nichols and Robin L. Lickteig

Address Post Office Box 328, George, IA 51237

Number and Street or RR

City, Town or P.O.

State

Zip

**Address of Property Transferred:**

2398 Cumming Road, Winterset, IA 50273

Number and Street or RR

City, Town, or P.O.

State

Zip

Legal Description of Property: (Attach if necessary) Lot Five (5) of Copper Fox Estates Subdivision located in the East Half (E 1/2) of the Southeast Quarter (SE 1/4) of Section Seventeen (17) in Township Seventy-nine (79) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa.

**1. Wells (check one)**

- There are no known wells situated on this property.
- There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

**2. Solid Waste Disposal (check one)**

- There is no known solid waste disposal site on this property.
- There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

**3. Hazardous Wastes (check one)**

- There is no known hazardous waste on this property.
- There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

**4. Underground Storage Tanks (check one)**

- There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
- There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

**5. Private Burial Site (check one)**

- There are no known private burial sites on this property.
- There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

**6. Private Sewage Disposal System (check one)**

- All buildings on this property are served by a public or semi-public sewage disposal system.
- This transaction does not involve the transfer of any building.
- There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
- This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: \_\_\_\_\_.
- The private sewage disposal system has been installed within the past two years pursuant to permit number \_\_\_\_\_.

**Information required by statements checked above should be provided here or on separate sheets attached hereto:**

See Inspection Report (DNR) Form 542-0191) attached

---



---



---



---

**I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.**

Signature: *Randall J. Jordan* Telephone No.: (515) 462-3865  
(Transferor or Agent)



Bank

**Time of Transfer Inspection Report (DNR Form 542-0191)**

Property information

Current owner Randy Jordan - 2912-Cedar Ridge Rd. Winterset, Mo 65273  
Buyer \_\_\_\_\_ Realtor Private sale  
Mailing address \_\_\_\_\_

Site Address/County 2398-Cumming Rd. Winterset, Mo. 65273 Madison Co -  
Legal Description \_\_\_\_\_

No. of bedrooms 4 Last occupied? is now Records available yes

Permit/installation date aug-2006 Separation distances ok/ no? OK  
L-133-06

Septic system information

Septic tank(s): size 2000 gal material concrete condition Very good  
Tank pumped? yes date 9-28-10 licensed pumper Murray ST. 75  
Septic/trash/processing tank: size \_\_\_\_\_ material \_\_\_\_\_ condition \_\_\_\_\_  
Tank pumped? \_\_\_\_\_ date \_\_\_\_\_ licensed pumper \_\_\_\_\_

Aerobic treatment unit (ATU) mfg \_\_\_\_\_ size \_\_\_\_\_  
Tank pumped? \_\_\_\_\_ date \_\_\_\_\_ licensed pumper \_\_\_\_\_  
Maintenance contract? \_\_\_\_\_ expiration date \_\_\_\_\_ service provider \_\_\_\_\_  
Condition \_\_\_\_\_

Pump tanks/vaults: type \_\_\_\_\_ size \_\_\_\_\_ condition \_\_\_\_\_

Distribution system: distribution box Plastic outlets used 5 condition Very good  
Header pipe(s) 4 # of lines 5 Pressure dosed? \_\_\_\_\_

Secondary treatment:  
length of absorption fields 100 ft determined by walking & probing  
condition of fields Very good determined by walking & probing  
type of trench material Chamber E-9-24

Size of sand filter \_\_\_\_\_ determined by \_\_\_\_\_  
Vent pipes above grade? \_\_\_\_\_ discharge pipe located? \_\_\_\_\_  
Effluent sample taken? \_\_\_\_\_ Results \_\_\_\_\_

Media filters: type \_\_\_\_\_  
Maintenance contract? \_\_\_\_\_ expiration date \_\_\_\_\_ service provider \_\_\_\_\_  
Condition \_\_\_\_\_

NPDES General Permit No. 4: required? \_\_\_\_\_ permitted? \_\_\_\_\_ NOI provided \_\_\_\_\_

Pictures on Back



### Time of Transfer Inspection Report

Other components:

Alarms \_\_\_\_\_ Working? \_\_\_\_\_ disinfection \_\_\_\_\_ working? \_\_\_\_\_

Control box \_\_\_\_\_ Timers \_\_\_\_\_ inspection ports \_\_\_\_\_

Other components \_\_\_\_\_

#### Overall condition of the private sewage disposal system

Report system status The septic system at 2398 Cummins Rd Winterset, Ia is in Very good Cond. the septic tank was Pumped on 9-28-10 - also no cracks in tank Explain (attach additional pages as needed): also tank has two compartments in tank & cut flow baffles are in place - on 9-28-10 - tank was added water to lateral field

Comments: Took water & none came to ground surface on 9-28-10 - also lateral hop was uncovered & opened & was in good Cond. also all gray water goes to septic tank on 9-28-10 -

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Yes Revisit all components to verify lids are secure.
- Done Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface. None on 9-28-10

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: John W. Mayer Date: 9-28-2010  
 Name (print): \_\_\_\_\_ Certificate #: 8979  
 Address: **JOHN MAYER**  
**SEPTIC TANK PUMPING**  
 Phone #: 515-462-2624 **1509 St. Hwy. 92**  
**Winterset, IA 50273-8411**


Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;

Iowa DNR Onsite Wastewater Program  
502 E. 9<sup>th</sup> St.  
Des Moines, IA 50319

*Map on Back →*

North ↑

Randy Jordan  
Copper Estates  
FOX Estates



5- 100 ft lines