

Document 2011 GW2342

Book 2011 Page 2342 Type 43 001 Pages 7 Date 9/02/2011 Time 1:30 PM

Rec Amt \$.00

INDX V ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

Name Terry L. Morrison and Connie M. Morrison					
Address 1088 State Hwy 92, Winterset, IA 50273					
Number and Street or RR	City, Town or P.O.	State	Zip		
TRANSFEREE:					
Name Timothy J. Rutter and Sandra D.	Rutter				
Address 1496 Quailridge Ave., Van Me	eter, IA 50261 City, Town or P.O.	State	Zip		
Address of Property Transferred: 1088 State Hwy 92, Winterset, IA 5027	3				
Number and Street or RR	City, Town, or P.O.	State	Zip		
Legal Description of Property: (Attach if	necessary) See Attached				
 Solid Waste Disposal (check one) X There is no known solid waste d	on this property. The type(s), local attached separate sheet, as neces disposal site on this property. Site on this property and information is document. aste on this property. Its property and information related document. ck one)	sary. on related thereto is thereto is provided (Note exclusions so	provided in uch as		
There is an underground storage	e tank on this property. The type(* * *			

5.	Private Burial Site (check one)		
	\underline{X} There are no known private burial sites on this property.		
	There is a private burial site on this property. The location(s) of the site(s) and known		
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as		
	necessary.		
6.	Private Sewage Disposal System (check one)		
	All buildings on this property are served by a public or semi-public sewage disposal system. This transaction does not involve the transfer of any building.		
	 There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.		
	permit number		
	ormation required by statements checked above should be provided here or on separate		
sn	eets attached hereto: Bored well 10 feet UE of house could be		
_	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	used. Not probled up anylonger. House has rural		
	(1) ates		
	ξολ. (100.100.100.100.100.100.100.100.100.100		
_			
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM		
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.		
Sig	nature: Leng Morvisor Telephone No.: (515) 240-1085		

Parcel "C" located in the Northeast Quarter (1/4) of the Northeast Quarter (1/4) of Section Seven (7) and the Southeast Quarter (1/4) of the Southeast Quarter (1/4) of Section Six (6), all in Township Seventy-five (75) North, Range Twenty-nine (29) West of the 5th P.M., Madison County, Iowa, containing 3.003 acres, as shown in Plat of Survey filed in Book 2004, Page 1301 on March 26, 2004, in the Office of the Recorder of Madison County, Iowa,



Time of Transfer Inspection Report

Property Information

Current Owner: Comit + Terry Morcison			
Buyer: Tinothy + Sandra Rutter Realtor: John Show / In Realty			
Mailing Address: 1088 Huy 90, Winterset In 50273			
Site Address/County: 1088 Hung 92, Winferset In 50273 / Madistry Co.			
Legal Description Pac C 34 2.95 A NE Sec. 7+,05 A SE6			
No. of bedrooms: 2 Last occupied: Currently Records available: 1/6			
Permit/ installation date: 3/9/05 Separation distances (60/no?):			
Septic System Information			
Septic tank(s): Size: 1000 Material: Concete Condition: Good			
Tank pumped? XY N Date: 8/02/11 Licensed pumper: Farest Septic			
Septic/Trash/Processing tank: Size: Material: Condition:			
Tank pumped?			
Aerobic treatment unit (ATU) mfgr			
Tank pumped? YN Date: Licensed pumper.			
Maintenance contract? \[\sum N \] Expiration date: \[\sum Service provider: \]			
Condition:			
Pump tanks/vaults: Type: Size: Condition:			
Distribution system: Distribution box X Outlets used 3 Condition: Gued			
Header pipe(s): No. of lines: Pressure dosed?			
Secondary Treatment:			
Length of absorption fields: 300' Determined by: Drawing			
Condition of fields: Determined by: Probing			
Type of trench material: Chambers			
Size of sand filter: Determined by:			
Vent pipes above grade? ☐ ▼ ☐ N Discharge pipe located? ☐ Y ☐ N			
Effluent sample taken Results:			
Media Filters: Type:			
Maintenance contract?			
Condition:			
NPDES General Permit No. 4: Required?			

1088 Hwy 92, Winterset 50273 Time of Transfer Inspection Report

Other components:		
Alarms: YN Working: YN Disinfection: YN Working: YN		
Control Box: Timers: Inspection Ports:		
Other components:		
Overall condition of the private sewage disposal system:		
Report system status: See A Hached Copy		
Explain (attach additional pages as needed):		
Comments:		
Site status at conclusion of Time of Transfer inspection:		
 Verify that controls are set on the appropriate mode. 		
 Power is on to all components. Revisit all components to verify lids are secure. 		
Gather all tools for removal from the site.		
Verify that no sewage is on the ground surface.		
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.		
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.		
Signature of Certified Inspector: Ct-Mile Date: 8/02/11		
Name (print): Cheis Mershon Certificate #: 5963		
Address: P.O. Box 219, Indiask In 50125		
Phone #: 515-745-5299		
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:		
Iowa DNR		
Private Sewage Disposal Program 502 E 9 th St		

Des Moines IA 50319

DNR Time of Transfer Report System Status

Address:	1088 Huy 92 Winterset In 50273 Date: 8/00/11
Comments:	Technician diple
	All Weste Liter In Home Drains To Septic System
	Septie Tank Is Quagarterest ust, Tax In
	Good Condition, Nist Bux Is Plastic
	In Good Condition, Laterial Field Pochal
	Dry Ad Took Water Well At Tompot Inspection
	* This To Not A Consenter. This States The Carlitain #
**************************************	* This Is Not A Garantee, This States The Contition & of Septic System At Time of Inspection.
*·····	

DIAGRAM OF SYSTEM

See Attached Copy

1088 State Highway 92, Winterset 50273

