

Document 2012 GW401

Book 2012 Page 401 Type 43 001 Pages 6 Date 2/09/2012 Time 2:05 PM

Rec Amt \$.00

I NDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

Address	400 Locust Street, Ste. 380	Des Moines	lowa	50309
	Number and Street or RR	City, Town or P.O.	State	Zip
TRANSF	EREE:			
Name	WAVO Properties, L.P.			
Address	5121/2 East Grand Avenue, Ste. 2	200 Des Moines	lowa	50309
	Number and Street or RR	City, Town or P.O.	State	Zip
A -1 -1	of Duran auto Transformed			
Address of Property Transferred: 1444 Walnut Lane		Cumming	lowa	50061

Legal Description of Property: (Attach if necessary)

Lot Four (4) of Knoufs Rural Estates Sub-District, a subdivision of the Southwest Quarter (1/4) of the Northeast Quarter (1/4) of Section Twenty-five (25), in Township Seventy-seven (77) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa.

City, Town or P.O.

1. Wells (check one)

Number and Street or RR

X There is a well situated on this property. The type, location and legal status are stated below.

2. Solid Waste Disposal (check one)

X There is no known solid waste disposal site on this property.

3. Hazardous Wastes (check one)

X There is no known hazardous waste on this property.

4. Underground Storage Tanks (check one)

- X There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
 - (s) contained are listed below or on an attached separate sheet, as necessary.

State

Zip

5.	Private Burial Site (check one)				
	X There are no known private burial sites on this property.				
6.	6. Private Sewage Disposal System (check one) All buildings on this property are served by a public or semi-public sewage disposal system. This transaction does not involve the transfer of any building. X There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording. There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form. There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. There is a building served by private sewage disposal system on this property. The building which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9] This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: The private sewage disposal sy				
	ormation required by statements checked above should be provided here or on separate eets attached hereto:				
	The well is a farm well located 20 feet from the intersection of the second entrance to the property discussed Walnut Lane Road.				
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.				
Sig	Inature: Telephone No.: 515-288-6440				

Thomas Bros. Septic Service

5731 SE 6th Ave
Des Moines, IA 50327
Froudly serving central Jowa over 55 years

02/07/12

Inspection report for property located at 1444 Walnut Ln. in Madison County. I looked at this system back in Sept of 2011. We were called out to service the tank and open a line. At the time of the service we uncovered the distribution box and found the d box in good condition. The tank has 2 compartments and is 1000 gallons in size. Also at the time of service we loaded the field and found the field working properly. At the time of the inspection the system was in good working condition.

Larry Thomas

Certified Inspector

NEHA Certified Installer

Thomas Bros Septic

515-681-1178

The findings in this report are not any guarantee of the future performance of this system. The findings are based on observations of the system at the time and day of the inspection only. Thomas Bros. will not be held liable for any hidden or unforeseen damages to this septic system. The inspection has been performed in accordance with the guidelines set forth by the Iowa DNR and in compliance with IAC567-chapter 69. All septic systems require regular maintenance and eventually require repairs.



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information				
Current owner PONACO MCBRIDE (TRUST)				
Buyer Realtor				
Mailing address				
Site Address/County 1444 Wacut W Comming, IA MADISON Legal Description				
No. of bedrooms Z Last occupied? (Linea) Records available No.				
Permit/installation date UN (now Separation distances ok/ no? 91)				
Septic system information				
Septic tank(s): size 1000 gr/ material Concrete condition 0/				
Tank pumped? Yes date 9/2011 licensed pumper THOMAS BROS.				
Septic/trash/processing tank: size material condition				
Tank pumped? date licensed pumper				
rank paintpea: danc neersea primper				
Aerobic treatment unit (ATU) mfgr size				
Aerobic treatment unit (ATU) mfgr size				
Tank pumped? date licensed pumper				
expiration date service provider				
Condition				
Pump tanks/vaults: type size condition				
Distribution system: distribution box X outlets used Condition				
Header pipe(s) # of lines Pressure dosed? \(\triangle \triangle \)				
1 1000 de 1000 .				
Secondary treatment:				
Secondary treatment: length of absorption fields // determined by Hudhaull (OA) condition of fields // determined by Hudhaull (OA)				
condition of fields OK determined by Hydracuc (OA)				
condition of fields <u>OK</u> determined by <u>HydracUC (CA)</u> type of trench material <u>ROCK Pipe</u>				
type of denot material 70000				
Size of sand filter determined by				
Vent pipes above grade? discharge pipe located?				
Effluent sample taken? Results				
Accounts and a second				
Media filters: type				
Maintenance contract? expiration date service provider				
Condition				



Time of Transfer Inspection Worksheet

Other components:	• \
Alarms Working?	disinfection working?
Control box Timers	inspection ports
Other components	· · · · · · · · · · · · · · · · · · ·
Overall condition of the private sewage dispo	sal system
Vefore sharms	
Explain (attach additional pages as needed):	
Comments: System in work	ing Condition etime
of this inspection	
- 01 +413 143pe C11010	
Site status at conclusion of Time of Transfer	increation
	~
• Verify that controls are set on	
Power is on to all components.	
Revisit all components to verify	
 Gather all tools for removal from 	· · · · · · · · · · · · · · · · · · ·
 Verify that no sewage is on the 	e ground surface.
Using this worksheet, write a narrative report	of the inspection results and attach a site sketch.
This report indicates the condition of the priv the inspection. It does not guarantee that it w	
THE IMPOSION IN COME HOL STREET, AND	in Symmetry to reflection sensite to the
Signature of Certified inspector:	Date: 2 7/12
Name (print): / ARRY Thomas	Certificate #: 9009
Address: 5721 SE 69 Av. (
Provide a copy of this report, the narrative rep	port and sketch to the seller/agent, buyer/agent, the in the county the inspection was conducted and to;
Iowa DNR Onsite Wastewater Program	
502 E. 9 th St.	
Des Moines, IA 50319	•

14114 WOLDUS LN.

(umning), FA

MADISON CO. cy¹ July John NACNUT 6 (Sparker Bang