

Book 2012 Page 2411 Type 43 001 Pages 7 Date 8/17/2012 Time 9:19 AM

Rec Amt \$.00

INDX **ANNO** SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

#### **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT** TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name

John Linhart

Address

15145 Highway 69, Weldon, IA 50264

Number and Street or RR

City, Town or P.O.

TRANSFEREE:

Name

Casey W. Christensen

Address

PO Box 41, Truro, IA 50257 Number and Street or RR 50257 City, Town or P.O.

State

Zip

Address of Property Transferred:

2953 Truro Road, Truro, IA 50257

Number and Street or RR

City, Town, or P.O.

State

Zip

Legal Description of Property: (Attach if necessary)

See Addendum

1. Wells (check one)

There are no known wells situated on this property.

There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

There is no known solid waste disposal site on this property.

There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

There is no known hazardous waste on this property.

\_\_ There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)

There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

5. Private Burial Site (check one)
$ \underline{\checkmark}$ There are no known private burial sites on this property.
There is a private burial site on this property. The location(s) of the site(s) and known
identifying information of the decedent(s) is stated below or on an attached separate sheet, as
necessary.
6. Private Sewage Disposal System (check one)
All buildings on this property are served by a public or semi-public sewage disposal system.
This transaction does not involve the transfer of any building which has or is required by law
to have a sewage disposal system.
There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natura Resources. A certified inspection report must be accompanied by this form when recording.  There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgmen with the county board of health to conduct a certified inspection of the private sewage disposal system as identified by the certified inspection A copy of the binding acknowledgment is attached to this form.  There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property. The building acknowledgment is provided with this form.  There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
This property is exempt from the private sewage disposal inspection requirements pursuan
to the following exemption:[Note: for exemption #9 use prior check box]
The private sewage disposal system has been installed within the past two years pursuant to
permit number
Information required by statements checked above should be provided here or on separate sheets attached hereto:
LIPPENV REALARE THAT LIBUR REVIEWED THE MARRIAGON TAR THE COLOR
I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND
THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Signature
Signature ( 10 h 2048 Telephone No.: (515) 210 - 8048

### Addendum

Parcel "A" located in the Northeast Quarter (1/4) of the Southeast Quarter (1/4) of Section Ten (10), Township Seventy-four (74) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa, containing 4.45 acres, as shown in Plat of Survey filed in Book 2005, Page 4867 on October 7, 2005 in the Office of the Recorder of Madison County, Iowa, EXCEPT any part thereof conveyed for road purposes or for use as a public highway.



# **Time of Transfer Inspection Report**

T .	* *	
Property	intown	OTION
TII H MT. IIV	345569648	7111611
T TO DOTE		

Current Owner: John Linbort 515-210-8048
Buyer: Realtor: Healter Sterr war 1743
Mailing Address: 3953 Truce Read Truco Ia 50357
Site Address/County: 2953 Tours Doad madison county
Legal Description Obio Township
No. of bedrooms: 3 Last occupied: Records available:
Permit/ installation date: 159-05 12-16-05 Separation distances (ok/no?):
Septic System Information
Septic tank(s): Size: 1,500 gal Material: Doly Condition:
Tank pumped? XY N Date: 4.31-12 Licensed pumper: 45. 57 307
Septic/Trash/Processing tank: Size: Material: Condition:
Tank pumped?
Aerobic treatment unit (ATU) mfgr Size
Tank pumped?
Maintenance contract?
Condition:
Pump tanks/vaults: Type: Size: Condition:
Distribution system: Distribution box Outlets used Condition:
Header pipe(s): No. of lines: 4 Pressure dosed?
Secondary Treatment:
Length of absorption fields: $4 \times 100 = 400 $ Determined by:
Condition of fields: excellent Determined by:
Type of trench material: 24 sch infiltratored Chambers
Size of sand filter: Determined by:
Vent pipes above grade?
Effluent sample taken Results:
Media Filters: Type:
Maintenance contract?
Condition:
NPDES General Permit No. 4: Required?



## **Time of Transfer Inspection Report**

Other components:
Alarms: Y N Working: Y N Disinfection: Y N Working: Y N
Control Box: Timers: Inspection Ports:
Other components:
Overall condition of the private sewage disposal system:
Report system status:
Explain (attach additional pages as needed):
•
Comments: have Septic Tank pumped and Cleaned every 3005 peop
clear effect filter once or twice argent.
Site status at conclusion of Time of Transfer inspection:
<ul> <li>Verify that controls are set on the appropriate mode.</li> <li>Power is on to all components.</li> </ul>
<ul> <li>Revisit all components to verify lids are secure.</li> <li>Gather all tools for removal from the site.</li> </ul>
Verify that no sewage is on the ground surface.
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.
Signature of Certified Inspector: Vance January Date: 4.25.12
Name (print): Uance Smith Certificate #: 8992
Address: 502 west Main Street St. Charles In 50240
Phone #: 641. 396. 2440
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office in the county the inspection was conducted, the county recorder and to:
Iowa DNR Onsite Wastewater Program 502 E 9 <sup>th</sup> St
Dec Mainer IA 50210

### ANYTIME SEPTIC SERVICES II VANCE SMITH 502 WEST MAIN ST. ST. CHARLES, IA. 50240 641-396-2440

On April 21, 2012 Anytime Septic Services II did Time of Transfer Real Estate Inspection on septic tank, distribution box and absorption field. At 2953 Truro Road in Truro, Iowa. John Linhart residence. I pumped and cleaned two chambered 1,500 gallon Poly Vinyl Fralo septic tank, and 500 gallon Poly Vinyl Fralo pump tank and refilled both tanks with clean tap water to level. The primary septic tank is in excellent condition with inlet and outlet baffles. There is a 4 inch effluent filter on the outlet side of primary septic tank that should be cleaned at least once or twice a year. The pump tank has a one horse powered Zoeller pump with an easy disconnect. Alarm system is on a wooden post next to pump tank and hard wired to breaker box inside of house and is working properly. The pump tank is pumping 396 feet up hill through 1 1/4 inch pipe to a plastic Tuf Tite distribution box with baffle supported with concrete. There are 4 headers leaving distribution box equally through speed levelers going to 24 inch infiltrator chambers that are 100 feet each, equaling 400 feet. There is no sign of effluences ponding or surfacing at ground level. There are two cleanout ports from house to septic tank. Both septic tanks and pump tank have 28 inch cleanout lids at ground surface, and the complete system was piped with schedule 40 piping.

SEPTIC TANK PUMPED ON 4-21- 2012 SYSTEM AND TANK INSPECTED AND ALL APPEARS TO BE IN GOOD WORKING ODER ON 4-21-2012

DISCLAIMER-ANYTIME SEPTIC SERVICES II IS NOT RESPONIABLE FOR ANY FAILED SEPTIC SYSTEMS

Parimit # 159-05 Linhart 54 Tank + Lateral Inspection 12/16/05 to be inspected Later