

Document 2012 GW3679

Book 2012 Page 3679 Type 43 001 Pages 6 Date 12/05/2012 Time 4:05 PM

Rec Amt \$.00

INDX V **ANNO SCAN** 

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

#### **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**

TO BE COMPLETED BY TRANSFEROR

	ISFEROR:	1 77 (0 )			
Name Addre					
Addie	Number and Street or RR	City, Town or P.O.	State	Zip	
		ony, round it is.	Olate	219	
	ISFEREE:	A NI C'III'			
Name					
Addre	ss 2794 Pioneer Avenue, Peru	u, IA 50222			
	Number and Street or RR	City, Town or P.O.	State	Zip	
	ss of Property Transferred:	14 50272			
2518	Millstream Avenue, Winterset,	IA 50273			
	Number and Street or RR	City, Town or P.O.	State	Zip	
ادمو ا	Description of Property: (Attacl	h if nacassanı)			
		nt 134 feet 7 inches North of the southwest corner of	the North Half (N ½) of the No	orthwest Quarter	
		y-five (75) North, Range Twenty-seven (27) West of			
		thence West 327 feet 3 inches, thence South 187 fee			
				<del></del>	
1. We	ells (check one)		,		
<u>X</u>	💆 There are no known wells situ				
_		ed on this property. The type(s), loc		tus are	
		n attached separate sheet, as neces	ssary.		
	lid Waste Disposal (check or	•			
<u>_X</u>	There is no known solid waste disposal site on this property.				
		al site on this property and informati	on related thereto is p	provided	
	in Attachment #1, attached to	this document.			
	zardous Wastes (check one)	ata an this muse sub.	•		
	There is no known hazardous		d the ameter to many date of t	_	
	<del></del>	this property and information related	a thereto is provided i	n	
4 Hn	Attachment #1, attached to th derground Storage Tanks (cl				
		ound storage tanks on this property.	(Note evaluaione au	sh oo	
<u></u>		tor fuel tanks, most heating oil tanks			
	,	age tank on this property. The type	(c) cizo(c) and any la	2014/2	
		sted below or on an attached separa			

5.	Private Burial Site (check one)
	X There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
6.	Private Sewage Disposal System (check one)
	<ul> <li>All buildings on this property are served by a public or semi-public sewage disposal system.</li> <li>This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.</li> <li>X There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.</li> <li>There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to</li> </ul>
	· · · · · · · · · · · · · · · · · · ·
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to permit number
<b>r</b>	
	ormation required by statements checked above should be provided here or on separate eets attached hereto:
) I I	sets attached hereto.
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
	nature: A Harvey 1/1 (21/2) Telephone No: (515) 229-1335
3iA	natura: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \



## Time of Transfer Inspection Report (DNR Form 542-0191)

Property information
Current Owner Francis & Debree Curter 229. 1335
Current Owner Francis + Debree Carter 239. 1335  Buyer Logan + Courtney Sillinen Realtor Attender Mark Smith 462.3731  Mailing Address 201 Description Peru Ta 50322
2794 Pioneer Ave.
Site Address/County 2518 Millstream, waterset Medicion county
No. of Bedrooms 3 Last Occupied? Signate Disposal? No. Softener? Y / P H2O Supply?
Records Available Permit/Installation Date 12-19-06 Installer
Septic System Information
Septic Tank(s): Size Size Material Condition
Septic Tank(s): Size
Sentic/Trash/Processing Tank: Size Material Condition
Tank pumped? Date Licensed Pumper
Aerobic treatment unit (ATU) MFGR Size
Aerobic treatment unit (ATU) MFGR Size Licensed Pumper Licensed Pumper
Maintenance Contract? Expiration Date Service Provider
Condition
Pump Ttanks/Vaults: Type Size Size Condition Condition Condition Condition Condition
Secondary Treatment  Length of Absorption Fields 5 x 50 = 380 Cost  Determined by  Condition of Fields  Type of Trench Material 36 inch in Filtrations
Length of Absorption Fields 5 x 50 = 380 Seet Determined by James Spatial
Condition of Fields excellent Determined by Value Facult
Type of Trench Material 316 in Ciltrators
Size of Sand Filter Determined by
Size of Sand Filter Determined by Vent Pipes Above Grade? Discharge Pipe Located?
Effluent Sample Taken? Results
Effluent Sample Taken? Results
Media Filters: Type
Media Filters: Type  Maintenance Contract? Expiration Date Service Provider  Condition
Condition
NPDES General Permit No. 4: Required? Permitted? NOI submitted



#### Time of Transfer Inspection Worksheet

# Other Components Alarms \_\_\_\_\_ Working? \_\_\_\_ Disinfection \_\_\_\_ Working? \_\_\_\_ Inspection Ports \_\_\_\_\_ Timers \_\_\_\_ Control Box Other Components Overall condition of the private sewage disposal system Acceptable? Unacceptable? Explain (attach additional pages as needed): Comments: Demp and Clean septie Tank wery 3 to 5 years Clear effluent filter at least once or horce rigers Site status at conclusion of Time of Transfer inspection: Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface. Using this worksheet, write a narrative report of the inspection results. Submit a copy of this report, including your narrative, to the city/county environmental health office, the DNR and the county Recorder in the county where the inspection was conducted. This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily. Signature of Certified Inspector: Date: 15-29-12 Name (print): Uznce Smith Certficate #: 3993 Address: 502 w nown street Statutes In 50240 Phone # 41. 396. 2440

10-2008 542-0191

### ANYTIME SEPTIC SERVICES II VANCE SMITH ST. CHARLES, IA 50240 641-396-2440

### REAL ESTATE SEPTIC INSPECTION

On October 24th, 2012 Anytime Septic Services II did Time of Tranfer Real Estate Inspection on septic tank, lift station, distribution box and laterial field at 2518 Millstream Ave. in Winterset, Iowa. The Francis and Debra Carter residence. The septic tank is a 1,500 gallon two compartment concrete Lister tank that I pumped & cleaned also cleaned 4 inch effluent filter. The septic tank is in excellent condition with inlet and outlet tee baffles. On the outlet side of septic tank is where the 4 inch effluent filter is located inside of tee baffle that should be cleaned at least once or twice a year, simply by lifting straight up from tee baffle and hosing clean with garden hose. Both inlet and outlet cleanout lids are both 22 inches in diameter and is 6 inches above ground level. The lift station is a 500 gallon concrete Lister tank that I also pumped and cleaned. The lift station contains a one horse powered pump, pumping through 2 inch pipe with an easy disconnect & is working properly, The alarm sounding system is located on the North wall in the basement. The distribution box is a plastic Tuf Tite box with tee baffle & supported with concrete 6 inches below ground level. There are 5 header lines leaving distribution box equally distributing effluence through speed levelers going into 36 inch infilterated chambers that are 56 feet each, equalling 280 total feet. There is no sign of efflunences ponding or surfacing at ground level. There are two cleanout ports from north side of house to septic tank. The complete system appears to have been piped with schedule 40 piping. Other than the 5 header lines leaving the distribution box are schedule 35 pipe.

ANYTIME SEPTIC SERVICES II IS NOT RESPONSIBLE FOR ANY FAILED SEPTIC SYSTEMS

2124625002>> 16413962440

HΞ

2012-10-12 11:48