

Book 2013 Page 1581 Type 43 001 Pages 6 Date 5/31 2013 Time 10:54 AM Rec Amt \$ 30

INDX V ANNO SCAN

CHEK

LISA SMITH, COUNTY RECORDER MADISON COUNTY TOWA


## **REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT**

TO BE COMPLETED BY TRANSFEROR

TRANSF Name	EROR: on Jackson and Ramona Jack	son (f/k/a Ramona Redman)	1	
*Address	2339 Valley View Ave.	St. Charles	IA	50240
	Number and Street or RR	City, Town or P.O.	State	Zip
TRANSF	EREE: Leonard O. Weaver and Cynth	ia I. Weaver		
Name	•			
Address <sub>-</sub>	3504 Blackhawk Dr. Number and Street or RR	Bellevue City, Town or P.O.	NE State	68123 Zip
Address	of Property Transferred: 2339 Valley View Ave.	St. Charles	IA State	50240
4 Wells	(abady ana)			
🎉 Th	(check one) ere are no known wells situated of		kiam/a) d la l -4	-A
	ere is a well or wells situated on t ated below or set forth on an attac			alus are
	Waste Disposal (check one)	strod doparato direct, ao ricoco		
	ere is no known solid waste dispo			
	ere is a solid waste disposal site tachment #1, attached to this doc		n related thereto is	provided in
	dous Wastes (check one)	dirion.		
	ere is no known hazardous waste			
	ere is hazardous waste on this pr		thereto is provided	in
	tachment #1, attached to this doc ground Storage Tanks (check o			
⊠ Th sr	ere are no known underground st nall farm and residential motor fue structions.)	orage tanks on this property. (		
□ Th	ere is an underground storage tar bstance(s) contained are listed be			

**FILE WITH RECORDER** 

DNR form 542-0960 (July 18, 2012)



5.	Pri	vate Burial Site (check one)
		There are no known private burial sites on this property.
		There is a private burial site on this property. The location(s) of the site(s) and known
		identifying information of the decedent(s) is stated below or on an attached separate sheet, as
_		necessary.
6.		vate Sewage Disposal System (check one)
		All buildings on this property are served by a public or semi-public sewage disposal system.
		This transaction does not involve the transfer of any building which has or is required by law to
		have a sewage disposal system.
	A	There is a building served by private sewage disposal system on this property or a building
		without any lawful sewage disposal system. A certified inspector's report is attached which
		documents the condition of the private sewage disposal system and whether any modifications
		are required to conform to standards adopted by the Department of Natural Resources. A
		certified inspection report must be accompanied by this form when recording.
		There is a building served by private sewage disposal system on this property. Weather or
		other temporary physical conditions prevent the certified inspection of the private sewage
		disposal system from being conducted. The buyer has executed a binding acknowledgment
		with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to
		the private sewage disposal system as identified by the certified inspection. A copy of the
		binding acknowledgment is attached to this form.
		There is a building served by private sewage disposal system on this property. The buyer has
		executed a binding acknowledgment with the county board of health to install a new private
		sewage disposal system on this property within an agreed upon time period. A copy of the
		binding acknowledgment is provided with this form.
		There is a building served by private sewage disposal system on this property. The building to
		which the sewage disposal system is connected will be demolished without being occupied. The
		buyer has executed a binding acknowledgment with the county board of health to demolish the
		building within an agreed upon time period. A copy of the binding acknowledgment is provided
		with this form. [Exemption #9]
		This property is exempt from the private sewage disposal inspection requirements pursuant to
		the following exemption [Note: for exemption #9 use prior check box]:
		The private sewage disposal system has been installed within the past two years pursuant to
		permit number
Inf	orn	nation required by statements checked above should be provided here or on separate
		s attached hereto:
	٠	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS
		FORM
		AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Sic	nat	ure: Danne Jackson Telephone No.: (515) 238-7736
- '2	,	(Transferor or Agent)

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)

## Addendum

1. Parcel "A", located in the Southeast Quarter (1/4) of the Northeast Quarter (1/4) of Section Nine (9), Township Seventy-five (75) North, Range Twenty-six (26) West of the 5<sup>th</sup> P.M., Madison County, Iowa, containing 4.571 acres, as shown in Plat of Survey filed in Book 3, Page 347 on November 17, 1998 in the Office of the Recorder of Madison County, Iowa.



Realton

## Time of Transfer Inspection Report (DNR Form 542-0191)

Property information
Current owner fon + Romona fackson  Buyer Realtor Magistan & Realty
Mailing address Realtor # STILLET OF NEARLY
Site Address/County 2339 Valleywiour ave It Charles, Legal Description
No. of bedrooms 3 Last occupied? in now Records available 4es
Permit/installation date 44-2000 Separation distances ok/no? 0 K
Septic system information
Septic tank(s): size 1500 gsl material concrete, condition 500 d  Tank pumped? yes date 5-8-13 licensed pumper Mayor \$575  Septic/trash/processing tank: size material condition  Tank pumped? date licensed pumper
Aerobic treatment unit (ATU) mfgr size  Tank pumped? date licensed pumper  Maintenance contract? expiration date service provider  Condition
Pump tanks/vaults: type size condition
Distribution system: distribution box <u>Plastio</u> outlets used <u>6</u> condition <u>Good</u> Header pipe(s) <u>5</u> # of lines <u>6</u> Pressure dosed?
Secondary treatment:  length of absorption fields 50 ff determined by must Profing determined by walking & Profing type of trench material 52 Chamber
Size of sand filter determined by
Vent pipes above grade? discharge pipe located?
Effluent sample taken? Results
Media filters: type  Maintenance contract? expiration date service provider  Condition
NPDES General Permit No. 4: required? permitted? NOI provided



Time of Transfer Inspection Report				
Other components:				
Alarms Working? disinfection working?				
Control box Timers inspection ports				
Other components				
Overall condition of the private sewage disposal system				
Report system status The septic system at 2339 Valley view are ft. Charles, da				
Explain (attach additional pages as needed): Is in good working Cond, The seption task				
Comments: intoke + autoflow baffles are in place. The fast loop was opened of all laterals tools water on 5-8-13- also lateral field was class tore				
one servage on groundlevel also all gray water goes to septing				
aboutes in tanh was at correct lessel before funging.  Site status at conclusion of Time of Transfer inspection: funging.				
Verify that controls are set on the appropriate mode.				
Power is on to all components.				
Revisit all components to verify lids are secure.  Gather all tools for removal from the site.				
• Verify that no sewage is on the ground surface.				
26				
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.				
8				
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.				
the hispection. It does not guarantee that it will continue to function satisfactority.				
Signature of Certified inspector 12013 \ Date: 5-10-2013				
Name (print): JOHN MAYER Certificate #: 2979				
Address:				
Phone # 373 962 2629 1 1509 St. Hwy. 92				
Winterset, IA 50273-8411  Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the				
county sanitarian/environmental health office county Recorder in the county the inspection was				
conducted and to;				
Iowa DNR Onsite Wastewater Program				
502 E. 9 <sup>th</sup> St.				
502 E. 9th St. Des Moines, IA 50319  Make on Backer  Make on Backer				

1 2 y oft Ext 35 324 - 45 104F WEST