

Document 2013 GW3124

Book 2013 Page 3124 Type 43 001 Pages 7 Date 10/16/2013 Time 11:09 AM Rec Amt \$ 00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

	TRANSFEROR: Name Adam L. Dahl and Courtney Dahl						
Address 1350 HWY 169, Winterset, IA 50273							
,	Number and Street or RR	City, Town or P.O.	State	Zip			
	ANSFEREE: me Jose Leon						
Ad	dress 2730 NW 157th St., Clive, IA 503	25					
,	Number and Street or RR	City, Town or P.O.	State	Zip			
	dress of Property Transferred: 50 HWY 169, Winterset, IA 50273						
	Number and Street or RR	City, Town, or P.O.	State	Zip			
Le	gal Description of Property: (Attach if n	ecessary) See Attached					
1.	Wells (check one) ☐ There are no known wells situated on this property.						
	There is a well or wells situated or stated below or set forth on an att.	this property. The type(s), loca		atus are			
2.	Solid Waste Disposal (check one) There is no known solid waste disposal site on this property.						
	There is a solid waste disposal site		n related thereto is	provided in			
3.	Attachment #1, attached to this do Hazardous Wastes (check one)	ocument.					
	☐ There is no known hazardous was	te on this property.					
	There is hazardous waste on this p		thereto is provided	in			
	Attachment #1, attached to this do						
4.	Underground Storage Tanks (check ☐ There are no known underground	•	Note evolucione cu	ch ac			
	small farm and residential motor finstructions.)						
	There is an underground storage t substance(s) contained are listed						

5.	Pri	vate Burial Site (check one)					
	X	There are no known private burial sites on this property.					
	П	There is a private burial site on this property. The location(s) of the site(s) and known					
	-	identifying information of the decedent(s) is stated below or on an attached separate sheet, as					
		necessary.					
6.	Pri	vate Sewage Disposal System (check one)					
		All buildings on this property are served by a public or semi-public sewage disposal system.					
		This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.					
	X	There is a building served by private sewage disposal system on this property or a building					
	γ.	without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.					
		There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the					
		binding acknowledgment is attached to this form.					
		There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.					
		There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the					
		building within an agreed upon time period. A copy of the binding acknowledgment is provided					
		with this form. [Exemption #9] This property is exempt from the private sewage disposal inspection requirements pursuant to					
		the following exemption [Note: for exemption #9 use prior check box]:					
		The private sewage disposal system has been installed within the past two years pursuant to permit number					
Inf sh	eets	nation required by statements checked above should be provided here or on separate state attached hereto: Well located in backyard, 55 of House					
		I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS					
	FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.						
		h = 1					
Siç	Signature: Mula Bul Adam Dahl Telephone No.: (515) 480-3698						

LEGAL DESCRIPTION

A tract of land located in the Northeast Quarter ($\frac{1}{4}$) of the Southeast Quarter ($\frac{1}{4}$) of Section Twenty-four (24), in Township Seventy-seven (77) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, more particularly described as follows, to-wit: Beginning at the Northwest corner of the Northeast Quarter ($\frac{1}{4}$) of the Southeast Quarter ($\frac{1}{4}$) of Section Twenty-four (24), thence East 1309.7 feet to the East Quarter ($\frac{1}{4}$) corner of said Section, thence South along the section line 495.56 feet, thence West 1308.8 feet to the West line of said Northeast Quarter ($\frac{1}{4}$) of the Southeast Quarter ($\frac{1}{4}$), thence North along said West line 495.56 feet to the point of beginning, Except the North 172 feet thereof



Time of Transfer Inspection Report

Property Information						
Current Owner: Adam & Courties DAHL						
Buyer: Jose Trinded Leon Realtor: John Antell - Re MAY						
Mailing Address: 228 Harries Village Plaulo Ky 41501						
Site Address/County: 1350 Huy 169 - MAdvon Co						
Legal Description AS ABSTRACT						
No. of bedrooms: 3 Last occupied: 1 mant 4 490 Records available: 45						
Remit installation date: 037-07-705 Separation distances (ok/no?):						
Septic System Information 1336						
Septic tank(s): Size: 1500 and Material: Concrete Condition: OK						
Tank pumped? YN Date: 9-23-13 Licensed pumper: Firest Soptic.						
Septic/Trash/Processing tank: Size: Material: Condition:						
Tank pumped?						
Aerobic treatment unit (ATU) mfgr Size						
Tank pumped? YN Date: Licensed pumper:						
Maintenance contract?						
Condition:						
Pump tanks/vaults: Type: Size: Condition:						
Distribution system: Distribution box VII Outlets used These Condition:						
Header pipe(s): No. of lines: Pressure dosed?						
Secondary Treatment:						
Length of absorption fields: S 150 Determined by: Lounty Records						
Condition of fields: O/C - DRy Determined by: PIZZaro 1 Hydralic						
Type of trench material: 10' (as Aveless p.p.) Test						
Size of sand filter: Determined by:						
Vent pipes above grade?						
Effluent sample taken Results:						
Media Filters: Type:						
Maintenance contract?						
Condition:						
NPDES General Permit No.4: Required? YN Permitted? YN NOI provided: 4/2010 cmz/dao DNR Form 542-0191						



Time of Transfer Inspection Report

Other components:							
Alarms: YN Working: YN Disinfection: YN Working: YN							
Control Box: Timers: inspection Ports:							
Other components:							
Overall condition of the private sewage disposal system:							
Report system status: See ASTOS							
Explain (attach additional pages as needed):							
Comments: fouse AAS NO BASEMENT.							
Site status at conclusion of Time of Transfer inspection:							
 Verify that controls are set on the appropriate mode. 							
 Power is on to all components. Revisit all components to verify lids are secure. 							
Gather all tools for removal from the site. Verify: that no source is on the ground purfece.							
Verify that no sewage is on the ground surface. Using this proclam at a process of the instantian and the stantian and							
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.							
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.							
Signature of Certified Inspector:							
Name (print): BRIAN KINARY Certificate #: 8805							
Address: PG. Bux 219 INSTANTIN TA 58135							
Phone #: 202-4805							
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person							
ordering the inspection, the county sanitarian/environmental health office and to:							
Iowa DNR							
Private Sewage Disposal Program 502 E 9 th St							
Des Moines lA 50319							

DNR Time of Transfer Report System Status

Address: 1350 Hwy 169 Date: 9-23-1	ځ
Comments: Technician Be AN	
Comments: Technician <u>Jec 4 w</u>	
All Wastewater From Horse Appair To	
90 INTO Septe System	
LOVO GARLON CONCRETE (2) Comparement Septe Trake	
with in working Condition	
PLASTIC DISTRUBUTION BOY WITH BATTLE AND Speed	<u>-</u>
Levelers used For (3) 100' Gravelless LATERAL	
Which All took WATER OK AT time OF	
the INSPECTION.	
TADS IS NOT A GUARANTER	D
THIS CENTILES The SOFTE SYSTOM	
WAS IN Working Condition AT	
the TIME OF the INSPECTION	
DIAGRAM OF SYSTEM	
300	
County	
Record	

1350 US Highway 169 Permit 037-07 TOS Permit 1330

bandoned well needs to be properly plugged.... 10" Gravelless John purtour surface grown and a character of sales be acted to not drawn to scale.....