

Book 2014 Page 1673 Type 43 001 Pages 6 Date 7/14/2014 Time 11:19 AM Rec Amt \$.00

INDX **ANNO SCAN**

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

TRANSF	EROR:							
Name	Frederick M. Csader and	Kelli A. Csader						
Address	3164 140th Street, Cumm	3164 140th Street, Cumming, IA 50061						
	Number and Street or RR	City, Town or P.O.	State	Zip				
TRANSF								
Name	Mark Brewick and Debra							
Address	4605 154th Street, Urband	lale, IA 50323		···-				
	Number and Street or RR	City, Town or P.O.	State	Zip				
	of Property Transferred: 0th Street, Cumming, IA 50	0061						
Nur	mber and Street or RR	City, Town or P.O.	State	Ζiρ				
X TI — TI st 2. Solid X TI	ated below or set forth on a Waste Disposal (check o n here is no known solid was	ted on this property. The type(s), loan attached separate sheet, as nece	essary.					
in 3. Hazar X TI At At Under X TI sr in	Attachment #1, attached to dous Wastes (check one) nere is no known hazardou here is hazardous waste or tachment #1, attached to the tachment #1 attached to the tachment #1 attached to the reground Storage Tanks (chere are no known undergrand) farm and residential mostructions.)	o this document. s waste on this property. In this property and information related in the comment.	ed thereto is provided in the control of the contro	n ch as tanks, in				
sı	ibstance(s) contained are li	sted below or on an attached separ	ate sheet, as necessar	ry.				

Э.	Filvate Durial Site (check one)
	X There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
6.	Private Sewage Disposal System (check one)
٠.	All buildings on this property are served by a public or semi-public sewage disposal system.
	This because does not involve the transfer of any highlier which has an exposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
•	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	X The private sewage disposal system has been installed within the past two years pursuant to
	permit number 542-0191
	permenantion <u>STZ-0171</u>
	ormation required by statements checked above should be provided here or on separate eets attached hereto:
	LHEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
	Telephone No.: 453-5387
Sig	nature: Telephone No.: 430-500
	(Yrankleredor Agent)
	FILE WITH RECORDER DNP form 542,0060 (Injur 49, 2042)



Time of Transfer Inspection Report

rtoperty information						
Current Owner: Fred q Kelli Csader						
Buyer: Markst Debra Brewick Realtor: Cole Alborght						
Mailing Address: Same Iowa Party						
Site Address/County: 3164 140th St. Cumming In. 50061						
Legal Description As Abstract						
No. of bedrooms: 3 Last occupied: Occupied Records available: 465						
Permit/ installation date: 10-25-04 Separation distances (ok/ho?):						
Septic System Information						
Septic tank(s): Size: 1500 gal Material: Conc. Condition: good						
Septic tank(s): Size: 1500 gal Material: Conc. Condition: good Tank pumped? N Date: 7-1-14 Licensed pumper: Farest Bestic ENV.						
Septic/Trash/Processing tank: Size: Material: Condition:						
Tank pumped? YN Date: Licensed pumper:						
Aerobic treatment unit (ATU) mfgr. Size						
Tank pumped?						
Maintenance contract?						
Condition:						
Pump tanks/vaults: Type: Size: Condition:						
Distribution system: Distribution box 425 Outlets used 4 Condition: gast						
Header pipe(s): No. of lines:Pressure dosed?						
Secondary Treatment:						
Length of absorption fields: 4 100' latter Determined by:						
Secondary Treatment: Length of absorption fields: 4 100' laterals Determined by: Arawing Condition of fields: 400 lay Determined by: hydraulie test						
Type of trench material: ovc / rock						
Size of sand filter: Determined by:						
Vent pipes above grade? YN Discharge pipe located? YN						
Effluent sample taken Results:						
Media Filters: Type:						
Media Filters: Type: Maintenance contract? Y N Expiration date: Service provider:						



Time of Transfer Inspection Report

Other components:							
Alarms: YN Working: YN Disinfection: YN Working: YN							
Control Box: Inspection Ports:							
Other components:							
Overall condition of the private sewage disposal system:							
Report system status: As attached							
Explain (attach additional pages as needed):							
Comments:							
Site status at conclusion of Time of Transfer inspection:							
 Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface. 							
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.							
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.							
Signature of Certified Inspector: But Told Date: 7-1-14							
Name (print): Brian Kinard Certificate #: 8805							
Address: P.O. Box 219 Ind In. 50125							
Phone #: 515-961 - 2113							
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:							
Iowa DNR							
Private Sewage Disposal Program 502 E 9 th St							
Des Moines IA 50319							

DNR Time of Transfer Report System Status

Address: 3164 140 thst.	_Date:	7+1-14
Address: 3164 140 thst. Comments: Technician L All waste water from house drains	Brien	Rinard
All waste water from house drains	+0	
septic system.		
The tonk is a 1500 gal. Conc	rete	tank
in good condition. The Distribution Fox 4 211	atan	-1,
The Distribution Fox 4 all lever in good working condition.	wer	ίζς
The good port of the contraction		
This is not a guarantee		
This centifies that the septic	54	rtem
was in pool working andition at		re_
Time A-V the inspection.		···
		······································
DIAGRAM OF SYSTEM		
LO MAN OF SYSTEM		

063-04 Csader Inspection 10/25/04 3164 140th Street

