

Document 2014 GW2712

Book 2014 Page 2712 Type 43 001 Pages 7 Date 10/31/2014 Time 11:32 AM Rec Amt \$.00 INDX

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSF	EROR:				
Name	Holly Frosch and Billy D.	Frosch			
Address	5154 Valley Farm Road, C	Central City, IA 52214			
	Number and Street or RR	City, Town or P.O.	State	Zip	
TRANSF	EREE:				
Name	David B. Vasey and Karen	J. Vasey			
Address	2893 Highway 169, Winter	set, IA 50273			
	Number and Street or RR	City, Town or P.O.	State	Zip	
	of Property Transferred: ritage Avenue, Lorimor, IA	50149			
Nur	mber and Street or RR	City, Town or P.O.	State	Zip	
Legal Description of Property: (Attach if necessary) The Northeast Quarter (NE 1/4) of the Northeast Quarter (NE 1/4) of Section Thirty-one (31), Township Seventy-four (74) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa.					
 Wells (check one) There are no known wells situated on this property. X There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary. Solid Waste Disposal (check one) X There is no known solid waste disposal site on this property. There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document. Hazardous Wastes (check one) 					
<u>X</u> T T At	here is no known hazardous	this property and information rela	ited thereto is provided	in	
<u>X</u> TI	here are no known undergro	und storage tanks on this propertor fuel tanks, most heating oil tar			

5.	Private Burial Site (check one)
	X There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
3.	Private Sewage Disposal System (check one)
•	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	X There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to
	permit number
	ormation required by statements checked above should be provided here or on separate
h	eets attached hereto:
<u>Ch</u>	ere is one well in southwest corner of property (windmill)
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
٠: -	Insture: 404 75524 Telephone No.: (641) 891-3311
VIII)	(CALLING 1974 * 1 1971 32 A LONG CONTROL DECORPORADO D

Kephart Construction 310 West Clanton Street St. Charles, IA. 50240 641-396-2239

October 29,2014

I was contacted to do a time of transfer inspection for a property at 3311 Heritage Ave., Lorimor, la. in Madison County.

I obtained information from Madison County Sanitarian. Reports show system was installed in 2003.

Tank was pumped by a licensed pumper on 10-17-14. A discharge sample was taken on 10-15-14 for B.O.D.

I visited the site for inspection and observed a 1500 gal. concrete Vanderpool tank with both lids at the surface. I uncovered and seen influent and effluent baffles were present, with an effluent filter. Center baffle was also present and all were in good shape.

Reports show a 18 x 40 sand filter 27 ft. from tank and signs of footprints are present, with two vent pipes located at outlet end. 55 ft. of discharge pipe were present and outlet is in good shape and discharging.

As of this time of inspection this is a good and working system in good shape. I would suggest to the new owners to clean effluent filter under 2nd lid in tank once a year, and obtain a maintence provider for a sampling of B.O.D. for Madison County and pump the tank every 3 years.

Kephart Construction

Kephart Construction

Clint Kephart

Chirt Kaphart

Certified Inspector

IOWWA Certified Installer

515-210-5677

The findings in this report are not any guarantee of the future performanance of this system. The findings are based on the observations of the system at the time & day of the inspection only. Kephart Construction will not be liable for any hidden or unforseen damages to this system. The inspection has been performed in accordance with the guidelines set forth by the Iowa DNR & in compliance with IAC567-Chapter 69. All septic systems require regular maintenance & eventually require repairs.



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information
Current owner
Current owner
Buyer ? Realtor Madison Co. Realty
Mailing address Larry Corknew
Site Address/County 3311 Heritage Ave., Lorinor, Ja Legal Description Malison County
Legal Description Madeson County
No. of bedrooms Last occupied? Records available
Permit/installation date 2003 Separation distances ok/ no? 6K
Septic system information
Septic tank(s): size 1500 Gal. material concrete condition good Tank pumped? Yes date 10-17-14 licensed pumper 5T 307 Septic/trash/processing tank: size — material — condition — Tank pumped? — date — licensed pumper —
Aerobic treatment unit (ATU) mfgr size
Pump tanks/vaults: type size condition
Distribution system: distribution box outlets used condition Header pipe(s) # of lines Pressure dosed?
Secondary treatment: length of absorption fields determined by condition of fields determined by ype of trench material
Size of sand filter 18 x 40 determined by <u>MADECTION</u> Vent pipes above grade? 2 discharge pipe located? <u>YED</u> Effluent sample taken? 10-15-14 Results < 2
Media filters: type
PDES General Permit No. 4: required? — permitted? — NOI provided



Time of Transfer Inspection Report

Alarms Working? disinfection working?
Control box inspection ports
Other components
Overall condition of the private sewage disposal system
Report system status good working condition See attached re
Explain (attach additional pages as needed):
Comments:
Site status at conclusion of Time of Transfer inspection: Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface.
Using this worksheet, write a narrative report of the inspection results and attach a site sketch. This report indicates the condition of the private sewage disposal system at the time of
Signature of Certified inspector: Name (print): Address: 202 State War Certificate #: 8977 Address: Chartes From Hard Continue to function satisfactorily. Date: 10-27-2014 Certificate #: 8977 Certificate #: 8977 Certificate #: 8977 Address: Chartes TA 50210 Phone # (515) 210 - 5677
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;
owa DNR Onsite Wastewater Program 502 E. 9 th St.



Analyte

State Hygienic Laboratory

The University of Iowa

VANCE SMITH 502 W MAIN ST SAINT CHARLES, IA 50240

Accession Number 197580 Date Sample Finalized 2014-10-23 11:01 Date Received 2014-10-16 11:34 Sample Source Non-Drinking Water Project Date Collected 2014-10-15 11:20 Collection Site outside Collection Town LORIMOR Sample Description Client Reference Collector | smith vance Phone 515/208-0167

Note: Sample exceeded required temperature upon receipt.

Results of Analyses

BOD, 5 Day, SM 5210 B

Units | mg/L Date Analyzed | 2014-10-17 07:15 Analyst | MGB Analyzed In Ankeny
Date Verified 2014-10-23 11:01
Verifier DLS

BOD, 5 Day <2 2

Result

Description of Units used within this report mg/L = Milligrams per Liter

The result(s) of this report relate only to the items analyzed. This report shall not be reproduced except in full without the written approval of the laboratory.

Iowa Environmental Laboratory IDs are: Ankeny #397, Iowa City/Coralville #027, Lakeside #393.

If you have any questions, please call Client Services at 800/421-IOWA (4692) or 319/335-4500. Thank you.