

Document 2016 GW681

Book 2016 Page 681 Type 43 001 Pages 7 Date 3/22/2016 Time 2:49:56PM Rec Amt \$.00

INDX ANNO **SCAN**

CHEK

LISA SMITH, COUNTY RECORDER

MADISON COUNTY IOWA

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSF Name		milton-Dix, Co-Executors of the Es	state of Jack Truman V	ierling
		q., 6701 Westown Pkwy Ste 100, W		
	Number and Street or RR	City, Town or P.O.	State	Zip
TRANSF				
Name	Hazel St. John	4 TA 50072		
Address	1902 - 8th Avenue N, Win			
	Number and Street or RR	City, Town or P.O.	State	Zip
	of Property Transferred: h Avenue N, Winterset, IA	50273		
Nun	nber and Street or RR	City, Town or P.O.	State	Zip
X TI	(check one) nere are no known wells sit			
 There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary. Solid Waste Disposal (check one) There is no known solid waste disposal site on this property. There is a solid waste disposal site on this property and information related thereto is provided 				
in	Attachment #1, attached to	this document.		provided
X TI	dous Wastes (check one) nere is no known hazardou: nere is hazardous waste on tachment #1, attached to th	s waste on this property. n this property and information relate	ed thereto is provided	in
TI sr in:	nall farm and residential mostructions.)	theck one) ound storage tanks on this property otor fuel tanks, most heating oil tank rage tank on this property. The type	ks, cisterns and septic	tanks, in
		sted below or on an attached separ		

5.	Private Burial Site (check one)
	★ There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
6.	Private Sewage Disposal System (check one)
	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to
	permit number
	permit number
	ormation required by statements checked above should be provided here or on separate eets attached hereto:
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
	nature: Telephone No.: 5/5-462-4940
Się	Inature: Telephone No.: 5/5 - 462 - 477

Addendum

1. Parcel "C" in the Southeast Quarter (SE1/4) of the Northwest Quarter (NW1/4) in the Northeast Quarter (NE1/4) of the Southwest Quarter (SW1/4) of Section Twenty-Five (25), Township Seventy-Six (76) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, containing 3.000 acres, as shown in Plat of Survey filed in Book 2003, Page 7151 on December 3, 2003, in the Office of the Recorder of Madison County, Iowa.



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information
Current owner Jack Vierling Estate Buyer Realtor Pat Corkson 515-468-1233 Mailing address us west Jeccerson St. Wolferset Ja 50213
Current owner Sacr Discount Production of the Contract of the
Buyer Realtor Park Congress 15-405-1255
Site Address/County 1902 North 8th Ase wholersof modison Country
Legal Description
No. of bedrooms A Last occupied? Jan. 2015 Records available 429
Permit/installation date 5.11.49 Separation distances OR/no?
1787
Septic system information
Septic tank(s): size 1,000 gallon material concrete condition excellent
Tank pumped?es date 3-8-14 licensed pumperes 5.T. 307
Septic/trash/processing tank: size material condition
Tank pumped? date licensed pumper
tank pumper date
Aerobic treatment unit (ATU) mfgr size Tank pumped? date licensed pumper
Tank pumped? date licensed pumper
Maintenance contract? expiration date service provider
Condition
Pump tanks/vaults: type size condition
Distribution system: distribution box <u>yes</u> outlets used <u>condition excellent</u> Header pipe(s) # of lines 3 Pressure dosed? <u>condition excellent</u>
. Header pipe(s) # of files Tressure desert:
Secondary treatment:
length of absorption fields 3 x 100' 300 ft. determined by lattice function
condition of fields Very Good determined by Vasstight
type of trench material 10" Graveless
Size of sand filter determined by
Vent pipes above grade? discharge pipe located?
Effluent sample taken? Results
Media filters: type
Maintenance contract? expiration date service provider
Condition
NPDES General Permit No. 4: required? permitted? NOI provided
MENES Actions Letiturian 4. redution: beamined: 1401 broades



Time of Transfer Inspection Worksheet

Other Components				
Alarms 00 Working? Disinfection 00 Working?				
Control Box Inspection Ports				
Other Components One.				
Overall condition of the private sewage disposal system				
Acceptable? Unacceptable?				
Explain (attach additional pages as needed):				
Commente: Decrees and I I I I I I I I				
Comments: Recommend to have Septic tank Proposed and Cheaned every 3 to 5 years				
Site status at conclusion of Time of Transfer inspection:				
Verify that controls are set on the appropriate mode. Power is on to all components.				
Revisit all components to verify lids are secure. Gather all tools for removal from the site.				
Verify that no sewage is on the ground surface.				
Using this worksheet, write a narrative report of the inspection results.				
Submit a copy of this report, including your narrative, to the city/county environmental health office, the DNR and the county Recorder in the county where the inspection was conducted.				
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.				
Signature of Certified Inspector: Date: 3-9.16				
Name (print): Uance Smith Certificate #: 18992				
Address: 502 west Mars Street St. Charles To 50240				
Phone # 641. 396. 2440				

10-2008

542-0191

ANYTIME SEPTIC SERVICES II VANCE SMITH ST. CHARLES, IA 50240 641-396-2440

REAL ESTATE SEPTIC INSPECTION


On March 8th, 2016 Anytime Septic Services II did Time of Transfer Real Estate Inspection on Septic tank, Distribution box and Lateral field at 1902 North 8th Ave. Winterset, Iowa 50273. Jack Vierling residence. Septic tank is a 1,000 gallon two compartment Lister tank that I pumped and cleaned with clean water. On both Inlet and Outlet ends of tank are 12 inch round concrete Lids above 4 inch schedule 40 piped Tee baffles with drops, Inlet is 15 inches below ground surface and Outlet is 10 inches below ground surface. Primary access clean out Lid is a 26 inch round concrete Lid and is 12 inches below ground surface 3/4 length of tank directly above separation wall inside of Septic tank. Septic tank is in excellent condition.

Distribution box is a plastic Tuff Tite box, I also pumped and cleaned with clean water and is 12 inches below ground surface with concrete surrounding for support, box is in excellent condition. Inside Distribution box is a 4 inch schedule 40 piped Tee baffle and 3, 4 inch schedule 35 piped lines leaving Distribution box through 3 speed levelers equally distributing Effluence's into Lateral field.

Lateral field consist of 3 runs of 10 inch Graveless drainage tite with a fabric sock and are 18 to 19 inches below ground surface. Each of the 3 runs are 100 feet each totaling 300 feet of Laterals with no evidence of any ponding or surfacing nor popping sound from probing above Absorption field.

OT RESPOSIBLE FOR ANY FAILED SEPTIC SYSTEMS.

7emit = 1787 5/11/77 1902 N BM AVE



111

16413962440

12/13/2010 20:31