

Document 2016 GW2083

Book 2016 Page 2083 Type 43 001 Pages 5 Date 7/19/2016 Time 11:55:34AM

Rec Amt \$.00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENTTO BE COMPLETED BY TRANSFEROR

TRANSF	EROR:					
Name	Hubz Adventures, LLC					
Address	2371 - 300th Street, Peru, IA 50222					
	Number and Street or RR	City, Town or P.O.	State	Zip		
TRANSF	EREE:					
Name	Fredrick D. Mersberger and	l Lauren M. Mersberger				
Address 1711 - 210th Street, Winterset, IA 50273						
	Number and Street or RR	City, Town or P.O.	State	Zip		
	of Property Transferred: 10th Street, Winterset, IA 50	0273	to to to to.			
Nur	mber and Street or RR	City, Town or P.O.	State	Zip		
	(check one)					
\overline{X} TI		d on this property. The type(s), loc		tus are		
		attached separate sheet, as neces	ssary.			
	Waste Disposal (check one	e) e disposal site on this property.				
		al site on this property and information	on related thereto is r	provided		
	Attachment #1, attached to					
	dous Wastes (check one)					
	here is no known hazardous					
There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.						
	rground Storage Tanks (ch					
<u>X</u> TI sn	here are no known undergro	und storage tanks on this property. for fuel tanks, most heating oil tanks	•			
TI	here is an underground stora	age tank on this property. The type				

5.	Private Burial Site (check one)					
	X There are no known private burial sites on this property.					
	There is a private burial site on this property. The location(s) of the site(s) and known					
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as					
	necessary.					
6.	Private Sewage Disposal System (check one)					
	All buildings on this property are served by a public or semi-public sewage disposal system.					
	This transaction does not involve the transfer of any building which has or is required by law to					
	have a sewage disposal system.					
	There is a building served by private sewage disposal system on this property or a building					
	without any lawful sewage disposal system. A certified inspector's report is attached which					
	documents the condition of the private sewage disposal system and whether any modifications					
	are required to conform to standards adopted by the Department of Natural Resources. A					
	certified inspection report must be accompanied by this form when recording.					
	There is a building served by private sewage disposal system on this property. Weather or					
	other temporary physical conditions prevent the certified inspection of the private sewage					
	disposal system from being conducted. The buyer has executed a binding acknowledgment					
	with the county board of health to conduct a certified inspection of the private sewage disposal					
	system at the earliest practicable time and to be responsible for any required modifications to					
	the private sewage disposal system as identified by the certified inspection. A copy of the					
	binding acknowledgment is attached to this form.					
	There is a building served by private sewage disposal system on this property. The buyer has					
	executed a binding acknowledgment with the county board of health to install a new private					
	· · · · · · · · · · · · · · · · · · ·					
	sewage disposal system on this property within an agreed upon time period. A copy of the					
	binding acknowledgment is provided with this form.					
	There is a building served by private sewage disposal system on this property. The building to					
	which the sewage disposal system is connected will be demolished without being occupied. The					
	buyer has executed a binding acknowledgment with the county board of health to demolish the					
	building within an agreed upon time period. A copy of the binding acknowledgment is provided					
	with this form. [Exemption #9]					
	This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]:					
	The private sewage disposal system has been installed within the past two years pursuant to					
	permit number					
	- Commence of the commence of					
Inf	formation required by statements checked above should be provided here or on separate					
	neets attached hereto:					
	ne well on west side of residence					
_						
_						
I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM						
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.					
Si	gnature: Cery MUS Telephone No.: (515) 975-9559					
	(Transferer or Agent)					

A tract of land located in the Southwest Quarter (1/4) of the Southwest Quarter (1/4) of Section Twenty-nine (29), Township Seventy-six (76) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, more particularly described as follows, to wit: Commencing at the Southwest corner of said Section Twenty-nine (29), running thence East 7.50 chains, thence North 6.66 chains, thence West 7.50 chains, thence South 6.66 chains to the point of beginning;

AND

A tract of land located in the Southwest Quarter (1/4) of the Southwest Quarter (1/4) of Section Twenty-nine (29), Township Seventy-six (76) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, more particularly described as follows, to wit: Commencing 7.5 chains East of the Southwest corner of said Section Twenty-nine (29), running thence East 5 chains 33 links, thence North 2 chains 67 links, thence West 5 chains 33 links, thence South 2 chains 67 links to the point of beginning.

Permit No 022-15 Name: Hubby 911 Sign Locate Date of Inspection: 5/18/15 Inspected by: Elton Contractor: Oxford Dwelling under construction or moved in Yes No							
Setbacks							
Meets required setbacks.							
 Rural Water Private wells/heat pump wells/suction water lines/lakes Outside required 50-foot setback for tank Outside required 100-foot setback for laterals Streams/ponds (25-25 ft)-ditches (10-10 ft) Indications of water lines under pressure Comments: 	Yes X Yes X Yes X Yes X Yes X Yes X	No					
 Building Sewer Clean outs – one right outside of house location of cleanout inside house and set requirement At Pipe is SCH 40 and has a 4-inch diameter. Grade – has adequate fall. Comments: 	Yes ☐ t basement wall e Yes ☑ Yes ☑	No 🔀 xit No 🗍 No 🗍					
 Tank Septic/Pump Tank Size & Manufacturer Lister 1500 Pump Tank Size & Manufacturer 	Concrete X Concrete	Plastic Plastic					
 Septic compartments meet the specs for capacity. Baffle Inlet/Outlet tees are ok. Effluent filter in the outlet. Yes No Ma Tank depth 12 inches 	Yes ⊠ Yes ⊠ Yes ⊠ anuf. Tuff tite red	No					
 Risers Lids above grade screwed on Comments: 	Yes ⊠ Yes □	No 🗌 No 🗍 Will be 🔀					
 Distribution Box Brand <u>Tuf-Tite</u> Other Bedded in cement. Has required inlet baffle. Outlet levels –are level. Comments: 	Yes⊠ Yes⊠ Yes⊠	No Will be No Unknown					
 Laterals Distribution lines: 4 -inch PVC pipe – SCH35 Lateral used. 36" Low profile Reduced Lateral depth. 30 inches Perc depth 30 inches Laterals were level. Adequate amount of undisturbed soil between laterals. Distance 6 feet between laterals. 	uction? Yes⊠ Yes∏	Yes No					

Comments:

Permit No 022-15 Name: Hubby 91 Date of Inspection: 5/18/15 Inspected by: Elton Contractor: Oxford Dwelling under construction or moved in Yes No	11 Sign Locate	
Setbacks		
Meets required setbacks.		
 Rural Water Private wells/heat pump wells/suction water lines/lakes Outside required 50-foot setback for tank Outside required 100-foot setback for laterals Streams/ponds (25-25 ft)-ditches (10-10 ft) Indications of water lines under pressure Comments: 	Yes X Yes X Yes X Yes X Yes X Yes X	No
 Building Sewer Clean outs – one right outside of house location of cleanout inside house and set requirement At I Pipe is SCH 40 and has a 4-inch diameter. Grade – has adequate fall. Comments: 	Yes ☐ basement wall e Yes ☑ Yes ☑	No 🔀 kit No 🔲 No 🗍
• • •	Concrete \(\sum \) Concrete \(\sum \)	Plastic Plastic
	Yes ⊠ Yes ⊠ Yes ⊠ nuf. Tuff tite red	No
 Tank depth 12 inches Risers Lids above grade screwed on Comments: 	Yes 🔀 Yes 🗌	No 🗌 No 🗌 Will be 🔀
Distribution Box Brand Tuf-Tite Other Bedded in cement. Has required inlet baffle. Outlet levels –are level. Comments:	Yes⊠ Yes⊠ Yes⊠	No Will be No Will be No Unknown
 Laterals Distribution lines: 4 -inch PVC pipe - SCH35 Lateral used. 36" Low profile Reduction Lateral depth. 30 inches Perc depth 30 inches Laterals were level. Adequate amount of undisturbed soil between laterals. Distance 6 feet between laterals. 	tion? Yes⊠ Yes□	Yes No

Comments: