



Document 2016 GW3079

Book 2016 Page 3079 Type 43 001 Pages 5

Date 10/17/2016 Time 12:44:07PM

Rec Amt \$.00

INDX  
ANNO  
SCAN

LISA SMITH, COUNTY RECORDER  
MADISON COUNTY IOWA

CHEK

**REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT  
TO BE COMPLETED BY TRANSFEROR**

**TRANSFEROR:**

Name Thomas A. Herold and Rebecca A. Herold, husband and wife

Address 625 42nd Street, Des Moines, IA 50312

Number and Street or RR

City, Town or P.O.

State

Zip

**TRANSFeree:**

Name Scott Reinhardt and Holly Reinhardt, husband and wife

Address 1408 Quail Ridge Avenue, Van Meter, IA 50261

Number and Street or RR

City, Town or P.O.

State

Zip

**Address of Property Transferred:**

1408 Quail Ridge Avenue, Van Meter, IA 50261

Number and Street or RR

City, Town or P.O.

State

Zip

**Legal Description of Property: (Attach if necessary)** A tract of land located in the Northwest Quarter (1/4) of the Northeast Quarter (1/4) of Section Twenty-six (26), Township Seventy-seven (77) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa, containing 8.5152 acres, as shown in Plat of Survey filed in Book 2, Page 449 on March 11, 1994, in the Office of the Recorder of Madison County, Iowa.

**1. Wells (check one)**

There are no known wells situated on this property.

There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

**2. Solid Waste Disposal (check one)**

There is no known solid waste disposal site on this property.

There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

**3. Hazardous Wastes (check one)**

There is no known hazardous waste on this property.

There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

**4. Underground Storage Tanks (check one)**

There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)

There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

**5. Private Burial Site (check one)**

- There are no known private burial sites on this property.
- There is a private burial site on this property. The location(s) of the site(s) and known identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary.

**6. Private Sewage Disposal System (check one)**


- All buildings on this property are served by a public or semi-public sewage disposal system.
- This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.
- There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording.
- There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form.
- There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form.
- There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9]
- This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: \_\_\_\_\_.
- The private sewage disposal system has been installed within the past two years pursuant to permit number \_\_\_\_\_.

Information required by statements checked above should be provided here or on separate sheets attached hereto:

There are two wells on the property; ① 70 feet NW of House - not operational;

② 200 feet South of house - functioning well.  
Both are marked with poles.

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:   
(Transferor or Agent)

Telephone No.: 10-14-16



Banks

**Time of Transfer Inspection Report (DNR Form 542-0191)**

Property information

Current owner Tom Harold & Rebecca Harold  
Buyer \_\_\_\_\_ Realtor Private  
Mailing address \_\_\_\_\_

Site Address/County 1408 - Quail Ridge Ave - Van Meter, La 50261  
Legal Description Madison Co

No. of buildings 3 Last occupied is now Records available yes

Permit # 113-03 Installation date 10/10/03 Inspection distance ok

Septic system information

Septic tank(s): size 1000 gal ea material Plastic concrete condition good  
Tank pumped? yes date 10/10/16 licensed pumper mafer septic

Septic/trash/processing tank: size \_\_\_\_\_ material \_\_\_\_\_ condition \_\_\_\_\_  
Tank pumped? \_\_\_\_\_ date \_\_\_\_\_ licensed pumper \_\_\_\_\_

Acrobic treatment unit (ATU) mfg \_\_\_\_\_ size \_\_\_\_\_  
Tank pumped? \_\_\_\_\_ date \_\_\_\_\_ licensed pumper \_\_\_\_\_

Maintenance contract? \_\_\_\_\_ expiration date \_\_\_\_\_ service provider \_\_\_\_\_  
Condition \_\_\_\_\_

Pump tanks/vaults: type \_\_\_\_\_ size \_\_\_\_\_ condition \_\_\_\_\_

Distribution system: distribution box Plastic outlets used 5 condition Good  
Header pipe(s) 4 # of lines 5 Pressure dosed? \_\_\_\_\_

Secondary treatment:

length of absorption fields 94' determined by map & probing  
condition of fields good & dry determined by walking & probing  
type of trench material Chamber

Size of sand filter \_\_\_\_\_ determined by \_\_\_\_\_  
Vent pipes above grade? \_\_\_\_\_ discharge pipe located? \_\_\_\_\_  
Effluent sample taken? \_\_\_\_\_ Results \_\_\_\_\_

Media filters: type \_\_\_\_\_  
Maintenance contract? \_\_\_\_\_ expiration date \_\_\_\_\_ service provider \_\_\_\_\_  
Condition \_\_\_\_\_

NPDES General Permit No. 4: required? \_\_\_\_\_ permitted? \_\_\_\_\_ NOI provided \_\_\_\_\_



### Time of Transfer Inspection Report

Other components:  
 Alarms \_\_\_\_\_ Working? \_\_\_\_\_ disinfection \_\_\_\_\_ working? \_\_\_\_\_  
 Control box \_\_\_\_\_ Timers \_\_\_\_\_ inspection ports \_\_\_\_\_  
 Other components \_\_\_\_\_

#### Overall condition of the private sewage disposal system

Report system status The septic system at 1408- Quail Ridge ave

Explain (attach additional pages as needed): Van Meter, Ia. 50261-  
is in good operating cond.

Comments: The (2) septic tanks were pumped on 10/10/16  
 the tanks are good cond. no cracks in tank slab  
 water at correct level before pumping.  
 All gray water goes to system on 10/10/16  
 The tank has (2) compartment intake & outflow baffles in place.  
 The distribution was opened & all laterals took water  
 but not in good cond.

#### Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Done  Revisit all components to verify lids are secure.
- Done  Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch Done on 10/10/16

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified inspector: John W. Mayer Date: 10/10/16  
 Name (print): JOHN MAYER Certificate #: 8979  
 Address: SEPTIC TANK PUMPING  
 Phone #: 515-462-2624 1509 St. Hwy. 92  
Winterset, IA 50278-8400

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;

Iowa DNR Onsite Wastewater Program  
 502 E. 9<sup>th</sup> St.  
 Des Moines, IA 50319

Permit # 113-03 Town Herald Inspection 10/10/03  
1408 Quail Ridge Ave.

