BK: 2017 PG: 2331 Recorded: 7/28/2017 at 3:50:36.0 PM

Fee Amount: \$0.00 **Revenue Tax:** 

**LISA SMITH RECORDER** Madison County, Iowa

## REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

TRANSFI	EROR:							
Name	Ryan J. Chapman and Kimberly A. Chapman							
Address	29204 Hickory Lodge Drive, Van Meter, IA 50261							
	Number and Street or RR	City, Town or P.O.	State	Zip				
TRANSFI	EREE:							
Name	Brett McDonough							
Address	3121 136th Ct., Cumming, IA 50061							
	Number and Street or RR	City, Town or P.O.	State	Zip				
3121 136	Property Transferred: 6th Ct., Cumming, IA 500 and Street or RR	City, Town or P.O.	State	Zip				
the North H		line (9) of St. John's Woods Subdivi It Quarter (1/4) of Section 22, Towns Ity, Iowa.	•					
Ther stated below 2. Solid Wa	e are no known wells situate e is a well or wells situated or set forth on an attached aste Disposal (check one) e is no known solid waste d	ed on this property. on this property. The type(s), location(separate sheet, as necessary. isposal site on this property. te on this property and information rela	, ,					
Attachment	#1, attached to this document							
<u>'</u> There	us Wastes (check one) is no known hazardous was							
	is hazardous waste on this #1, attached to this document	property and information related theretont.	is provided in					

FILE WITH RECORDER

DNR form 542-0960 (July 18, 2012)

4. Underground Storage Tanks (check one)	
There are no known underground storage tanks	
farm and residential motor fuel tanks, most heating oil There is an underground storage tank on this pro-	
substance(s) contained are listed below or on an attach	
5. Private Burial Site (check one)	ou separate sheet, as necessary.
There are no known private burial sites on this p	property
	the location(s) of the site(s) and known identifying
information of the decedent(s) is stated below or on an	
6. Private Sewage Disposal System (check one)	,,
All buildings on this property are served by a pu	olic or semi-public sewage disposal system.
This transaction does not involve the transfer of	
have a sewage disposal system.	, ,
There is a building served by private sewage disp	osal system on this property or a building without
any lawful sewage disposal system. A certified inspect	or's report is attached which documents the
condition of the private sewage disposal system and wh	ether any modifications are required to conform to
standards adopted by the Department of Natural Resou	ces. A certified inspection report must be
accompanied by this form when recording.	
There is a building served by private sewage disp	
temporary physical conditions prevent the certified insp	
being conducted. The buyer has executed a binding acl	•
conduct a certified inspection of the private sewage dis	
be responsible for any required modifications to the pri	
certified inspection. A copy of the binding acknowledg There is a building served by private sewage disp	
executed a binding acknowledgment with the county bo	
disposal system on this property within an agreed upon	
acknowledgment is provided with this form.	time period. At copy of the officing
There is a building served by private sewage disp	osal system on this property. The building to
which the sewage disposal system is connected will be	
executed a binding acknowledgment with the county bo	
agreed upon time period. A copy of the binding acknow	
#9]	
This property is exempt from the private sewage	
following exemption [Note: for exemption #9 use prior	
The private sewage disposal system has been inst	alled within the past two years pursuant to permit
number	
Information required by statements checked above s	hould be provided here or on separate sheets
attached hereto:	
I HEREBY DECLARE THAT I HAVE REVIEWE	D THE INSTRUCTIONS FOR THIS FORM
AND THAT THE INFORMATION STATE	
110	
$\langle \chi   I / \lambda$	
Signature: Ay Ly	Telephone No.: (515) 314-7566
(Transferor or Agent)	
PILE WITH RECORDER	DNR form 542-0960 (July 18, 2012)



## Time of Transfer Inspection Report (DNR Form 542-0191)

Current Owner	Ryan Chapman					
Buyer	Realtor Abbey Robertson					
Mailing Address 3121 136Th Ct, Cum	nming IA 50061					
Site Address/County 3121 136Th C	Ct, Cumming IA 50061 MADISON CO					
No. of Bedrooms Last Occupied	? currently Disposal? Y/N Softener? Y/N H <sub>2</sub> O Supply?					
Records Available Permit/Ins	tallation DateInstaller					
Septic System Information						
Septic Tank(s): Size 1500 gal.	Material Concrete Condition Working					
Tank Pumped? Yes Da	te 7-10-17 Licensed Pumper Forest Septic					
Septic/Trash/Processing Tank: Size_	Material Condition					
Tank pumped? Date	c pumped? Date Licensed Pumper					
Aerobic treatment unit (ATU) MFGI	Size Licensed Pumper   kpiration Date Service Provider					
Tank Pumped? Date	Licensed Pumper					
Maintenance Contract? Ex	spiration Date Service Provider					
Condition						
	Size Condition					
Heade	Number of Lines ConditionWorking re Dosed?					
Secondary Treatment						
Length of Absorption Fields 4x90ft=	360ft Determined by Drawling and probing					
Condition of Fields Working	Determined by Hydraulic load test					
Type of Trench Material Chambers						
Size of Sand Filter	Determined by Discharge Pine I control?					
Vent Pipes Above Grade?	Discharge Pipe Located?					
Effluent Sample Taken?	Results					
Maintenance Contract?	xpiration Date Service Provider					
Condition	spiration Date Service I tovider					
	red? Permitted? NOI submitted					

10-2008 542-0191




Time of Transfer Inspection Worksheet

	Other Components								
	Alarms	Working?	Disinfection	Working?					
	Control Box	Timers	Inspection Ports						
	Other Components _								
	Overall condition of	rall condition of the private sewage disposal system							
	Acceptable? YES	Unac	ceptable?						
Explain (attach additional pages as needed):  All waste water goes from house to septic. 1500 gal concrete tank with risers, outlet tee and filter in goo condition. Plastic distribution box in good working condition. Hydraulic load tested 4x90ft=360ft 36" characterists with 200 gal water. Laterals took all water and probed clean and dry at this time.									
Comments: This is not a guarantee, but a report of condition at time of inspection.  Site status at conclusion of Time of Transfer inspection:									
Using this worksheet, write a narrative report of the inspection results.									
	Submit a copy of this DNR and the county	s report, including your narrati Recorder in the county where	ive, to the city/county environth the inspection was conduct	onmental health office, the ed.					
	does not guarantee th	the condition of the private senat it will continue to function d Inspector:	satisfactorily.						
	Name (print): Rick	Rogers	Ce	rtficate #: 9597					
	Address: 401 NE Phone # 515-74	52nd Ave Des Moines IA 50313 45-8352							

10-2008 542-0191

Permit# 036-07 Chapman Inspection 10/11/07 3121 136th Ct.



Fe de .