

Book 2017 Page 4042 Type 43 001 Pages 7 Date 12/22/2017 Time 3:09:33PM

Rec Amt \$.00

INDX **ANNO SCAN**

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name	Charles G. Tadlock and Connie L. Tadlock						
	815 E. Court, Winterset, IA 50273						
	Number and Street or RR	City, Town or P.O.	State	Zip			
TRANSF	EREE:						
Name							
Address	2716 Millstream Ave, Peru, IA 50222						
	Number and Street or RR	City, Town or P.O.	State	Zip			
	of Property Transferred: llstream Ave, Peru, IA 5022	22					
Nur	nber and Street or RR	City, Town or P.O.	State	Zip			
2. Solid TI	ated below or set forth on a Waste Disposal (check o n here is no known solid was	ted on this property. The type(s), loo an attached separate sheet, as nece ne) te disposal site on this property. sal site on this property and informat	ssary.				
3. Hazar X Ti Ti At 4. Under	dous Wastes (check one) here is no known hazardou here is hazardous waste or tachment #1, attached to the rground Storage Tanks (chere are no known undergr	s waste on this property. In this property and information relate This document.	. (Note exclusions su	ıch as			
Ti		rage tank on this property. The type					

5 .	Private Buriai Site (check one)
	X There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
•	Private Sewage Disposal System (check one)
U.	
	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	X There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to
	permit number
Info	rmation required by statements checked above should be provided here or on separate
	ets attached hereto:
_	l is northwest of property near creek north of driveway
VV C	T IS HOLLIWEST OF PROPERTY HEAR CICER HOLLI OF CITYCWAY
Sen	tic - north of house - See attached
ООР	tio notal of notice bee attached
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
	,
	$\alpha = \alpha + \alpha$
Siar	nature: Marles D. Sallock Telephone No.: (515) 201-7401
اق. ح	(Transferor or Agent)

Addendum

1. A tract of land commencing at the Southwest Corner of the Northeast Quarter (1/4) of the Northeast Quarter (1/4) of Section Thirty-one (31) in Township Seventy-five (75) North, Range Twenty-seven (27) West of the 5th P.M., Madison County, Iowa, thence North 642 feet, thence Southeasterly 552 feet 6 inches to a point 615 feet Northeast of a point on the South line of said Northeast Quarter (1/4) Northeast Quarter 542 feet East of the Southwest Corner of said Northeast Quarter (1/4) Northeast Quarter (1/4), thence Southwesterly to a point on the South line of said Northeast Quarter (1/4) Northeast Quarter (1/4) 542 feet East of the Southwest corner thereof, thence West 542 feet to the point of beginning subject to easements and conveyances for highway and utility purposes.



Time of Transfer Inspection Report

Tioperty information
Current Owner: CHARLES & CONNIE TAdLock
Buyer: BLANdi 1 Joe Riedle Realtor: Sarah Cowmon
Mailing Address: 815 E Court Ave Winterset \$4 50273
Site Address/County: 2716 Milletteam Ave / MAdison Co
Legal Description AS ABSTRACT.
No. of bedrooms: 5 Last occupied: June 2017 Records available: Yes
Permit/ installation date: 051-05/ 5-19-05 Separation distances (ok/no?):
Septic System Information
Septic tank(s): Size: 2000 94/ Material: /6Ncrete Condition: 0t
Tank pumped? NY Date: 1/-20-17 Licensed pumper: Country Side Septie
Septic/Trash/Processing tank: Size:Material:Condition:
Tank pumped? Y N Date: Licensed pumper:
Aerobic treatment unit (ATU) mfgr Size
Tank pumped? Y N Date: Licensed pumper:
Maintenance contract?
Condition:
Pump tanks/vaults: Type: Size: Condition:
Distribution system: Distribution box 2-301's Outlets used 9 Total Condition: Of
Header pipe(s): No. of lines: Pressure dosed?
Secondary Treatment:
Length of absorption fields: (9) 50-60 Determined by: Probing
Condition of fields: OK - Day Determined by: ProBing & Hydralia
Type of trench material: Chamber
Size of sand filter: Determined by:
Vent pipes above grade?
Effluent sample taken Results:
Media Filters: Type:
Maintenance contract? N Expiration date: Service provider:
Condition:
NPDES General Permit No. 4: Required? YN Permitted? YN NOI provided:



Time of Transfer Inspection Report

Other components:
Alarms: YN Working: YN Disinfection: YN Working: YN
Control Box: Timers: Inspection Ports:
Other components: None
Overall condition of the private sewage disposal system:
Report system status: See AHAched pages
Explain (attach additional pages as needed):
Comments: House has Bean VAcant since June 2017
which may have an effect on results of Inspection
Site status at conclusion of Time of Transfer inspection:
 Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface.
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.
Signature of Certified Inspector: Date: 11-20-17
Name (print): Brian Rinard Certificate #: 8805
Address: P.O. Box 204 NORWALK IN 50211
Phone #: 515-202-4895
Frovide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:
Iowa DNR Private Sewage Disposal Program
502 E 9 th St Des Moines IA 50319


DNR Time of Transfer Report System Status

Address: 2716 Millstream Are	Date: 11-20-17
Comments: FAST PIRU, FA 50222 Technician	Brown
All WASTEWATER From House Appe	
SPAIN INTO SEPTIC SYSTEM.	
3,000 gallow lowerete 2 Companime	of Septic TANK
WITH RISECS I EFFEMENT FILTER WAS	
WORKING CONDITION	
2) Plastic DISTIUDUTION BOXES &	Both Had
BAFFLES AND ALSO BOTH had socied	Levelers use
BAFFLES AND Also Bott hap speed an All Lateral Live Both DISTRI	BUTTON BOX
Were in warking condition	
All (9) LATERALI TOOK WATER FO.	e 5-10 minures
AND PIOBED DRY AT TIME OF the I	
	7
THIS 15 NOT A GUARANTER	
THIS CEPTIFIED + that the SENTRE	system
WAS IN WORLDING CONDIFION AT	-1-16
time OF the INSPECTION	
DIAGRAM OF SYSTEM	
See	

County Records

4/2010 cmz/dao

DNR Form 542-0191



(,ONSHIRE