

BK: 2018 PG: GW2379
Recorded: 7/23/2018 at 3:47:59.0 PM
Fee Amount: \$0.00
Revenue Tax:
LISA SMITH RECORDER ✓
Madison County, Iowa ✓

This document is recorded to replace the original document file July 23, 2018 at Book 2018 Page 2378.

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT
TO BE COMPLETED BY TRANSFEROR

TRANSFEROR:

Name Archway Development Group, LLC
Address 2800 University Avenue, Suite 134, West Des Moines, IA 50266
Number and Street or RR City, Town or P.O. State Zip

TRANSFeree:

Name Justin Menke
Address 3361 178th Court, Norwalk, IA 50211
Number and Street or RR City, Town or P.O. State Zip

Address of Property Transferred:
3361 178th Court, Norwalk, IA 50211
Number and Street or RR City, Town or P.O. State Zip

Legal Description of Property: (Attach if necessary) Lot Seven (7) of Hogue Subdivision, an official plat of the Southwest Quarter (1/4) of the Southeast Quarter (1/4) and the North Half (1/2) of the Southeast Quarter (1/4) of the Southeast Quarter (1/4) of Section Twelve (12), Township Seventy-six (76) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa

1. Wells (check one)

- There are no known wells situated on this property.
 There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary.

2. Solid Waste Disposal (check one)

- There is no known solid waste disposal site on this property.
 There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document.

3. Hazardous Wastes (check one)

- There is no known hazardous waste on this property.
 There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document.

4. Underground Storage Tanks (check one)

- There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.)
 There is an underground storage tank on this property. The type(s), size(s) and any known substance(s) contained are listed below or on an attached separate sheet, as necessary.

GROUNDWATER HAZARD STATEMENT

ATTACHMENT #1

NOTICE OF WASTE DISPOSAL SITE

a. Solid Waste Disposal (check one)


- There is a solid waste disposal site on this property, but no notice has been received from the Department of Natural Resources that the site is deemed to be potentially hazardous.
- There is a solid waste disposal site on this property which has been deemed to be potentially hazardous by the Department of Natural Resources. The location(s) of the site(s) is stated below or on an attached separate sheet, as necessary.

b.. Hazardous Wastes (check one)

- There is hazardous waste on this property and it is being managed in accordance with Department of Natural Resources rules.
- There is hazardous waste on this property and the appropriate response or remediation actions, or the need therefore, have not yet been determined.

Further descriptive information:

I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.

Signature:  Telephone No.: (515) 745-1195
(Transferor or Agent)



Time of Transfer Inspection Report

Other components:

Alarms: Y N Working: Y N Disinfection: Y N Working: Y N

Control Box: no Timers: no Inspection Ports: no

Other components: none

Overall condition of the private sewage disposal system:

Report system status: Septic tank and distribution box appeared to be water tight and in good condition

Explain (attach additional pages as needed): see attached page

Comments: All plumbing from the house is directed to the septic tank. System appeared to be functioning properly at the time of inspection.

Site status at conclusion of Time of Transfer inspection:

- Verify that controls are set on the appropriate mode.
- Power is on to all components.
- Revisit all components to verify lids are secure.
- Gather all tools for removal from the site.
- Verify that no sewage is on the ground surface.

Using this worksheet, write a narrative report of the inspection results and attach a site sketch.

This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.

Signature of Certified Inspector: Tom Gardiner Date: 11/10/16

Name (print): Tom Gardiner Certificate #: 8794

Address: 2372 D Ave Perry, IA 50220

Phone #: 515 491-1188

Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office in the county the inspection was conducted, the county recorder and to:

Iowa DNR Onsite Wastewater Program
502 E 9th St
Des Moines IA 50319



Time of Transfer Inspection Report

Property Information

Current Owner: Bruce E Curtis - contact Witherwax Law, PC 515 224-5377
 Buyer: _____ Realtor: n/a Witherwax Law, PC 515 224-5377
 Mailing Address: 6205 Mills Civic Pkwy, Suite 201, West Des Moines, Ia 50266
 Site Address/County: 3361 178th Ct, Norwalk, IA 50211 / Madison
 Legal Description Lot 7 Hogue Sub-Div

No. of bedrooms: 2 Last occupied: July 2016 Records available: yes
 Permit/ installation date: 1066 / 7-14-82 Separation distances (ok/no?): ok

Septic System Information

Septic tank(s): Size: 1000 Material: concrete Condition: ok

Tank pumped? Y N Date: 11-10-16 Licensed pumper: A-1 Complete Septic

Septic/Trash/Processing tank: Size: n/a Material: _____ Condition: _____

Tank pumped? Y N Date: _____ Licensed pumper: _____

Aerobic treatment unit (ATU) mfg: n/a Size _____

Tank pumped? Y N Date: _____ Licensed pumper: _____

Maintenance contract? Y N Expiration date: _____ Service provider: _____

Condition: _____

Pump tanks/vaults: Type: n/a Size: _____ Condition: _____

Distribution system: Distribution box yes Outlets used 4 Condition: ok

Header pipe(s): 3 No. of lines: 4 Pressure dosed? no

Secondary Treatment:

Length of absorption fields: 4-lines, 63' each Determined by: County Diagram

Condition of fields: ok Determined by: visual and probing

Type of trench material: rock bedded pipe

Size of sand filter: n/a Determined by: _____

Vent pipes above grade? Y N Discharge pipe located? Y N

Effluent sample taken n/a Results: _____

Media Filters: Type: n/a


Maintenance contract? Y N Expiration date: _____ Service provider: _____

Condition: _____

NPDES General Permit No. 4: Required? Y N Permitted? Y N NOI provided: _____

3361 178th Ct.
Norwalk, IA
Madison Co.

N
N



Homegard Inspections Services, LLC
2372 D. Ave. Perry, Iowa 50220
515-491-1188

Date: 11-10-16
Time of Transfer Septic Inspection
3361 178th Ct, Norwalk, IA 50211

The septic system located at 3361 178th Ct, Norwalk, Ia, in Madison County was excavated for a complete inspection. The system consists of a 1000 gallon concrete septic tank, a concrete distribution box and 4 rock bedded laterals each approximately 63 feet in length for a total absorption field length of approximately 250'.

The septic tank and distribution box appeared to be water tight and in good condition at the time of the inspection. All components of the septic tank, (inlet, outlet baffles and center wall) are intact and functioning. The absorption field was hydraulically tested during the inspection using over 100 gallons of water. All 4 laterals accepted water equally with no apparent issues. The area of the absorption field was visually inspected and probed, showing no signs of excessive moisture. Vegetation over the absorption area appeared normal.

Note, a 4 inch PVC drain line has been installed directly over the septic tank and d-box. It appears to be a roof drain from the front of the house which is directed to the road ditch at the front of the property. This line was removed to gain access to the tank and d-box, and then replaced after completing the inspection.

The system appeared to be functioning properly at the time of inspection.



Tom Gardiner
IDNR Operator #8794