

Book 2018 Page 3064 Type 43 001 Pages 7 Date 9/21/2018 Time 10:15:20AM Rec Amt \$.00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

TRANSF Name	EROR: Richard E. Billeter			
Address				
	Number and Street or RR	City, Town or P.O.	State	Zip
TRANSF	EREE:			
Name	Larry D. Rutherford			
Address	1881 313th St, Lorimor, IA	50149		
	Number and Street or RR	City, Town or P.O.	State	Zip
	of Property Transferred: 8th St, Lorimor, IA 50149			
Nur	mber and Street or RR	City, Town or P.O.	State	Zip
T(_ <u>X</u> T(st 2. Solid T(T(3. Hazar T(ated below or set forth on ar Waste Disposal (check on here is no known solid waste here is a solid waste disposal Attachment #1, attached to dous Wastes (check one) here is no known hazardous	ed on this property. The type(s), local attached separate sheet, as necessive) e disposal site on this property. al site on this property and information this document. E waste on this property. this property and information related	sary.	provided
4. Under X TI sr in TI	rground Storage Tanks (chere are no known undergromall farm and residential mostructions.) here is an underground stora		cisterns and septions), size(s) and any k	tanks, in

5.	Priyate Burial Site (check one)			
	There are no known private burial sites on this property.			
	There is a private burial site on this property. The location(s) of the site(s) and known			
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as			
	necessary.			
6.	Private Sewage Disposal System (check one)			
•-	All buildings on this property are served by a public or semi-public sewage disposal system.			
	This transaction does not involve the transfer of any building which has or is required by law to have a sewage disposal system.			
	There is a building served by private sewage disposal system on this property or a building			
	without any lawful sewage disposal system. A certified inspector's report is attached which			
	documents the condition of the private sewage disposal system and whether any modifications			
	are required to conform to standards adopted by the Department of Natural Resources. A			
	certified inspection report must be accompanied by this form when recording.			
	There is a building served by private sewage disposal system on this property. Weather or			
	other temporary physical conditions prevent the certified inspection of the private sewage			
	disposal system from being conducted. The buyer has executed a binding acknowledgment			
	with the county board of health to conduct a certified inspection of the private sewage disposal			
	system at the earliest practicable time and to be responsible for any required modifications to			
	the private sewage disposal system as identified by the certified inspection. A copy of the			
	binding acknowledgment is attached to this form.			
	There is a building served by private sewage disposal system on this property. The buyer has			
	executed a binding acknowledgment with the county board of health to install a new private			
	sewage disposal system on this property within an agreed upon time period. A copy of the			
	binding acknowledgment is provided with this form.			
	There is a building served by private sewage disposal system on this property. The building to			
	which the sewage disposal system is connected will be demolished without being occupied. The			
	buyer has executed a binding acknowledgment with the county board of health to demolish the			
	building within an agreed upon time period. A copy of the binding acknowledgment is provided			
	with this form. [Exemption #9]			
	This property is exempt from the private sewage disposal inspection requirements pursuant to			
	the following exemption [Note: for exemption #9 use prior check box]:			
	The private sewage disposal system has been installed within the past two years pursuant to			
	permit number			
Inf	ormation required by statements checked above should be provided here or on separate			
sh	eets,attached, hereto:			
V	Vell is located West trom the house loo vards.			
1	North of Hay building 33 yards well is covered			
	and not in use			
_				
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM			
	AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.			
	/// 20 11/			
٠.	gnature: Multiple B. Jahren Telephone No.: 55-739 0176			
Sig	gnature:			





Time of Transfer Inspection Report

Property information
Current Owner: Richard & Gladeane Billeter
Buyer: Realtor:
Mailing Address:
Site Address/County: 1881 313th Street Joriman IA 50149
Legal Description
No. of bedrooms: 3 Last occupied: Apr. 1 2018 Records available: Yes
Permit/ installation date: 3-28-2007 Separation distances (ok/no?):
Septic System Information
Septic tank(s): Size: 1500 Material: Concrete Condition: good
Tank pumped? XY N Date: 6-25-18 Licensed pumper: 5+-237
Septic/Trash/Processing tank: Size: Material: Condition:
Tank pumped?
Aerobic treatment unit (ATU) mfgr Size
Tank pumped?
Maintenance contract?
Condition:
Pump tanks/vaults: Type: Size: Condition:
Distribution system: Distribution box $\rho_{\alpha + 1}$ Outlets used 6 Condition: α
Header pipe(s): No. of lines: Pressure dosed? no
Secondary Treatment:
Length of absorption fields: Determined by:
Condition of fields: Determined by:
Type of trench material:
Size of sand filter: LO`XZO` Determined by: WKG - Proble, reasuring W Vent pipes above grade? N Discharge pipe located? N
Vent pipes above grade? ✓ Y □ N Discharge pipe located? ✓ Y □ N
Effluent sample taken NO-not discharging Results:
Media Filters: Type:
Maintenance contract?
Condition:
NPDES General Permit No. 4: Required? TYTN Permitted? TYTN NOI provided:


542-0191



Time of Transfer Inspection Report

Other components:			
Alarms: Y N Working: Y N Disinfection: Y N Working: Y N			
Control Box: Timers: Inspection Ports: hone			
Other components:			
Overall condition of the private sewage disposal system: 6-00			
Report system status: System was working properly on day of inspection.			
Explain (attach additional pages as needed): System was working property on			
day of inspection.			
Comments: Spr attuched			
Site status at conclusion of Time of Transfer inspection:			
 Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. Verify that no sewage is on the ground surface. 			
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.			
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.			
Signature of Certified Inspector: Se Rod M Date: 7-25-18			
Name (print): Joe beduc! Certificate #: 10974			
Address: 1310 East Clinton Arenue Indianola IA 50/25			
Phone #: 515 - 681 - 5885			
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to:			
Iowa DNR			
Private Sewage Disposal Program 502 E 9 th St			
Des Moines IA 50319			

Permit # 015-07 Billeter 2nd Inspection



NO DISCHARGE SAMPLE FORM

l hereby certify	that I at	tempte	ed to obta	ain an eff	fluent samp	le from	the
onsite wastewate	er disch	arge p	oint at:				
		, in	11				

NAME:	Joe Bedwell
ADDRESS:	1881 313th Street
	Lorimor IA 50 149
ttempted to o	btain a sample of the above onsite wastewate

I attempted to obtain a sample of the above onsite wastewater system, but found no evidence of an effluent discharging. I inspected the system for any signs of surface discharge, erosion, soil staining, etc. There did not appear to be any evidence of flow in the last six months. I will continue to monitor the system in accordance with Iowa Administrative Code 567 - Chapter 69.2(455B) and Iowa Administrative Code 567 - Chapter 64, General Permit #4 Rules and the County specified sampling dates.

Upon inspection of the system, the discharge pipe is:

______ clean and cleared of debris
______ covered or I was unable to locate the discharge
______ other ______

DATE OF INSPECTION: ______ 6-2|-|8|

SAMPLER NAME: Joe Bedwell

MAINTENANCE CONTRACTOR (Company Name):

VIONE

1881 313th street

Lorimor, IA 50149

During my inspection I noticed that there is another septic system on the property that is left from an older home that is no longer there. I also wanted to make note that the lids to the current tank are cracked but are still secured to the risers. The house is currently vacant and may be another reason that the sand filter was not discharging upon inspection. The system was in working condition on the day of inspection.

Joe Bedwell