

Document 2018 GW3584

Book 2018 Page 3584 Type 43 001 Pages 5 Date 11/05/2018 Time 1:35:08PM

Rec Amt \$.00

INDX ANNO SCAN

LISA SMITH, COUNTY RECORDER MADISON COUNTY IOWA

CHEK

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT

TO BE COMPLETED BY TRANSFEROR

| TRANSF | EROR: | | | | |
|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------|------------------------------|-------------|-----------------------|-------------|
| Name | Jeffrey E. Hayes | | | | |
| Address | 1477 Warren Avenue, Cum | ming, IA 50061 | | | |
| | Number and Street or RR | City, Town or P.O. | | State | Zip |
| TRANSF | EDEE. | | | | |
| Name | Adam Daniel Weigert | | | | |
| | 2941 MAIN St | CHURCHVILLE | 1/4 | 50211 | _ |
| / ladi ooo j | Number and Street or RR | City, Town or P.O. | | State | Zip |
| | Number and Street of AA | City, Town of P.O. | | State | 210 |
| | of Property Transferred: | | | | |
| <u>1477 Wa</u> | arren Avenue, Cumming, IA | 50061 | | | |
| Nui | mber and Street or RR | City, Town or P.O. | | State | Zip |
| Logol Do | porintian of Property (Attack | if no coccond See 1 in Ad | dendum | | |
| Legal De | scription of Property: (Attach | ii necessary) _sec 1 iii 7td | dendam | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | (check one) | -kd | | | |
| | here are no known wells situate | | (no/o) loo | otion(a) and local at | ntuo oro |
| | here is a well or wells situate tated below or set forth on an | attached separate shoot | pe(s), loca | alion(s) and legal st | alus are |
| | Waste Disposal (check one | | , as neces | ssaiy. | |
| There is no known solid waste disposal site on this property. | | | | | |
| There is a solid waste disposal site on this property and information related thereto is p | | | | | provided |
| | Attachment #1, attached to t | his document. | | | • |
| 3. Hazardous Wastes (check one) | | | | | |
| | here is no known hazardous | | | | |
| | here is hazardous waste on t | | ion related | I thereto is provided | in |
| | ttachment #1, attached to this | | | | |
| | rground Storage Tanks (ch | | | (Nists susingless sus | |
| + | here are no known undergrou | and storage tanks on this | property. | (Note exclusions su | ion as |
| | mall farm and residential moto structions.) | or idertanks, most neating | y on lanks | , cisterns and septic | ; lanks, in |
| | here is an underground stora | ge tank on this property | The type/ | s) size(s) and any | mown |
| | ubstance(s) contained are list | | | | |
| • | | or some or on an attach | ou ocpaid | .c ccc., ac 1100033 | ٠٠ ٫ ٠ |

| 5. | Private Burial Site (check one) There are no known private burial sites on this property. There is a private burial site on this property. The location(s) of the site(s) and known |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| | identifying information of the decedent(s) is stated below or on an attached separate sheet, as necessary. |
| 6. | Private Sewage Disposal System (check one) |
| | All buildings on this property are served by a public or semi-public sewage disposal system. This transaction does not involve the transfer of any building which has or is required by law to |
| | have a sewage disposal system. X There is a building served by private sewage disposal system on this property or a building without any lawful sewage disposal system. A certified inspector's report is attached which documents the condition of the private sewage disposal system and whether any modifications are required to conform to standards adopted by the Department of Natural Resources. A certified inspection report must be accompanied by this form when recording. There is a building served by private sewage disposal system on this property. Weather or other temporary physical conditions prevent the certified inspection of the private sewage disposal system from being conducted. The buyer has executed a binding acknowledgment with the county board of health to conduct a certified inspection of the private sewage disposal system at the earliest practicable time and to be responsible for any required modifications to the private sewage disposal system as identified by the certified inspection. A copy of the binding acknowledgment is attached to this form. There is a building served by private sewage disposal system on this property. The buyer has executed a binding acknowledgment with the county board of health to install a new private sewage disposal system on this property within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. There is a building served by private sewage disposal system on this property. The building to which the sewage disposal system is connected will be demolished without being occupied. The buyer has executed a binding acknowledgment with the county board of health to demolish the building within an agreed upon time period. A copy of the binding acknowledgment is provided with this form. [Exemption #9] This property is exempt from the private sewage disposal inspection requirements pursuant to the following exemption [Note: for exemption #9 use prior check box]: The private sewage disposal system has been installed within the past two y |
| Inf | ormation required by statements checked above should be provided here or on separate |
| | eats attached harata: |
| _ | Well is locate approximulity 50° sorth of the Southenst |
| _ | Con 1 to at the house |
| _ | |
| Sig | I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT. Telephone No.: (515) 669-9918 |
| | |

Addendum

1. A tract of land located in the Southeast Quarter (1/4) of the Southeast Quarter (1/4) of Section 25, Township Seventy-seven (77) North, Range Twenty-six (26) West of the 5th P.M., Madison County, Iowa, more particularly described as follows: Commencing at the Northeast Corner of the the Southeast Quarter (1/4) of the Southease Quarter (1/4) of said Section Twenty-five (25), running thence South 38 rods, thence in a Northwesterly direction approximately 27 rods to a point 20 rods South of the North line of said Southeast Quarter (1/4) of the Southeast Quarter (1/4) thence North 20 rods to said North line, thence East approximately 21 rods to the point of beginning, and containing approximately 3.8 acres.





Time of Transfer Inspection Report

| Property Information |
|---------------------------------------------------------------------------------|
| Current Owner: Jeff Hayes |
| Buyer: Realtor: |
| Mailing Address: Sam€ |
| Site Address/County: 1477 Warren Avenue Cumming, IA 50061 |
| Legal Description |
| No. of bedrooms: 3 Last occupied: Current Records available: yes |
| Permit/ installation date: 6-24-75 Separation distances (ok/no?): OK |
| Scptic System Information |
| Septic tank(s): Size: 1000 Material: Concrete Condition: |
| Tank pumped? N Date: 10-12-18 Licensed pumper: 51-237 |
| Septic/Trash/Processing tank: Size: Material: Condition: |
| Tank pumped? |
| Aerobic treatment unit (ATU) mfgr Size |
| Tank pumped? Y N Date: Licensed pumper: |
| Maintenance contract? YN Expiration date: Service provider: |
| Condition: |
| Pump tanks/vaults: Type: Size: Condition: |
| Distribution system: Distribution box Concrete Outlets used 4 Condition: Broken |
| Header pipe(s): 3 No. of lines: Pressure dosed? |
| Secondary Treatment: |
| Length of absorption fields: 4 @ 90 Determined by: Map Prote, Measuring |
| Condition of fields: 9000, See description Determined by: hidraulic test |
| Type of trench material: rock and Pipe |
| Size of sand filter: Determined by: |
| Vent pipes above grade? |
| Effluent sample taken Results: |
| Media Filters: Type: |
| Maintenance contract? |
| Condition: |
| NIDDES Convert Bormit No. 4: Popping 19 N. N. Downitted 19 N. NOI provided. |





Time of Transfer Inspection Report

| Other components: | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--|--|
| Alarms: YN Working: YN Disinfection: YN Working: YN | | | | |
| Control Box: Timers: Inspection Ports: | | | | |
| Other components: none | | | | |
| Overall condition of the private sewage disposal system: OK | | | | |
| Report system status: System was working properly on day of inspection. Explain (attach additional pages as needed): The system has a broken distribution box. Other components working on day of inspection. Comments: Secondary treatment hendled hydraulic test. Ohe line Stopped taking water after 10 min. the rest took water Site status at conclusion of Time of Transfer inspection: Verify that controls are set on the appropriate mode. Power is on to all components. Revisit all components to verify lids are secure. Gather all tools for removal from the site. | | | | |
| Verify that no sewage is on the ground surface. | | | | |
| Using this worksheet, write a narrative report of the inspection results and attach a site sketch. | | | | |
| This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily. | | | | |
| Signature of Certified Inspector: Ledull Date: 10-12-18 | | | | |
| Name (print): Joe Bedwell Certificate #: 10974 | | | | |
| Address: 1310 Eust Clinton Arana Indianola IA 50125 | | | | |
| Phone #: 5/5-681-5885 | | | | |
| Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent or the person ordering the inspection, the county sanitarian/environmental health office and to: | | | | |
| lowa DNR Private Sewage Disposal Program 502 E 9th St Des Moines (A 50319 | | | | |