BK: 2019 PG: 1889

Recorded: 6/25/2019 at 10:04:48.0 AM

Pages 5

County Recording Fee: \$0.00 lowa E-Filing Fee: \$0.00 Combined Fee: \$0.00

Revenue Tax:

LISA SMITH RECORDER Madison County, Iowa

REAL ESTATE TRANSFER - GROUNDWATER HAZARD STATEMENT TO BE COMPLETED BY TRANSFEROR

TRANSFEROR: Bethene A. Boardman 1997 Declaration of Trust Name Address 2817 Clark Tower Rd. Peru. IA 50222 Number and Street or RR City, Town or P.O. State Zin TRANSFEREE: Name Leo Timothy O'Brien and Shayla Lea O'Brien Address 2463 Bittersweet Ave, Winterset, IA 50273 Number and Street or RR City, Town or P.O. State Zīp Address of Property Transferred: 2817 Clark Tower Road, Peru, IA 50222 Number and Street or RR City, Town or P.O. State Zin Legal Description of Property: (Attach if necessary) Parcel "B", located in the East Half (1/2) of the Northeast Quarter (1/4) of Section One (1), Township Seventy-four (74) North, Range Twenty-eight (28) West of the 5th P.M., Madison County, Iowa, containing 13.381 acres, as shown in Plat of Survey filed in Book 2003, Page 1057 on February 26, 2003, in the Office of the Recorder of Madison County, Iowa. 1. Wells (check one) There are no known wells situated on this property. ___ There is a well or wells situated on this property. The type(s), location(s) and legal status are stated below or set forth on an attached separate sheet, as necessary. 2. Solid Waste Disposal (check one) ✓ There is no known solid waste disposal site on this property. ___ There is a solid waste disposal site on this property and information related thereto is provided in Attachment #1, attached to this document. 3. Hazardous Wastes (check one) There is no known hazardous waste on this property. There is hazardous waste on this property and information related thereto is provided in Attachment #1, attached to this document. 4. Underground Storage Tanks (check one) There are no known underground storage tanks on this property. (Note exclusions such as small farm and residential motor fuel tanks, most heating oil tanks, cisterns and septic tanks, in instructions.) There is an underground storage tank on this property. The type(s), size(s) and any known

substance(s) contained are listed below or on an attached separate sheet, as necessary.

5.	Priyate Burial Site (check one)
	There are no known private burial sites on this property.
	There is a private burial site on this property. The location(s) of the site(s) and known
	identifying information of the decedent(s) is stated below or on an attached separate sheet, as
	necessary.
6.	Private Sewage Disposal System (check one)
	All buildings on this property are served by a public or semi-public sewage disposal system.
	This transaction does not involve the transfer of any building which has or is required by law to
	have a sewage disposal system.
	There is a building served by private sewage disposal system on this property or a building
	without any lawful sewage disposal system. A certified inspector's report is attached which
	documents the condition of the private sewage disposal system and whether any modifications
	are required to conform to standards adopted by the Department of Natural Resources. A
	certified inspection report must be accompanied by this form when recording.
	There is a building served by private sewage disposal system on this property. Weather or
	other temporary physical conditions prevent the certified inspection of the private sewage
	disposal system from being conducted. The buyer has executed a binding acknowledgment
	with the county board of health to conduct a certified inspection of the private sewage disposal
	system at the earliest practicable time and to be responsible for any required modifications to
	the private sewage disposal system as identified by the certified inspection. A copy of the
	binding acknowledgment is attached to this form.
	There is a building served by private sewage disposal system on this property. The buyer has
	executed a binding acknowledgment with the county board of health to install a new private
	sewage disposal system on this property within an agreed upon time period. A copy of the
	binding acknowledgment is provided with this form.
	There is a building served by private sewage disposal system on this property. The building to
	which the sewage disposal system is connected will be demolished without being occupied. The
	buyer has executed a binding acknowledgment with the county board of health to demolish the
	building within an agreed upon time period. A copy of the binding acknowledgment is provided
	with this form. [Exemption #9]
	This property is exempt from the private sewage disposal inspection requirements pursuant to
	the following exemption [Note: for exemption #9 use prior check box]:
	The private sewage disposal system has been installed within the past two years pursuant to
	permit number
sha	permation required by statements checked above should be provided here or on separate sets attached hereto: water well on property Downed, Investige, 150 yourds South of the house
	2. Ma. 1. 100 401 65
	South of the house
	I HEREBY DECLARE THAT I HAVE REVIEWED THE INSTRUCTIONS FOR THIS FORM AND THAT THE INFORMATION STATED ABOVE IS TRUE AND CORRECT.
Sig	nature: X My Brishma Telephone No.: (515) 419-1490



Time of Transfer Inspection Report (DNR Form 542-0191)

Property information

Current owner <u>Bob Board</u> man
Buyer 100 O'Brien Regitor Sole 1.
Current owner <u>Bob Board man</u> Buyer Leo O'Brien Realtor <u>Sale 64 owner</u> Malling address <u>2817 Clark tower</u> RJ Peru <u>TA</u> 50222
Site Address/County 2817 Clark Jower Rd Wintersut IA Legal Description Same as address
No. of bedrooms 3 Last occupied? 5-30-19 Records available 400
Permit/installation date 11/1/94 Separation distances 60 no?
Septic system information
Septic tank(s): size 1000 gal material Coment condition Looks of at this Tank pumped? Les date 6-4-19 licensed pumper 405 Country Side Time Septic/trash/processing tank: size no material condition Tank pumped? date licensed pumper
Aerobic treatment unit (ATU) mfgr // size
Pump tanks/vaults: type size condition
Secondary treatment: length of absorption fields 100ft & 4 determined by mapt place condition of fields 100ft & 4 determined by Dung up in Sports type of trench material 24" Charles
Size of sand filter determined by Vent pipes above grade? discharge pipe located? Effluent sample taken? Results
Media filters: type Maintenance contract? expiration date service provider Condition
NPDES General Permit No. 4: required? 122 permitted? NOI provided



Time of Transfer Inspection Report

Other components: Alarms Working? disinfection working?		
Control box 1/6 Timers 10 inspection parts 1/4		
Other components has clean out in yord		
Overall condition of the private sewage disposal system Report system status <u>hao 1000 gol</u> 2 <u>Compartment Cansent Tank</u>		
Comments:		
Site status at conclusion of Time of Transfer inspection:		
 Verify that controls are set on the appropriate mode. 		
Power is on to all components.		
 Revisit all components to verify lids are secure 		
 Gather all tools for removal from the site. 		
 Verify that no sewage is on the ground surface. 		
Using this worksheet, write a narrative report of the inspection results and attach a site sketch.		
This report indicates the condition of the private sewage disposal system at the time of the inspection. It does not guarantee that it will continue to function satisfactorily.		
Signature of Certified inspector: Allen Okaus Date: 6/3/19 Name (print): Allen Akars Certificate #: 203 Phone # 5/5/1/16/19 6/5/19		
Address: 2264 175 at Winterset 7A 50273 Phone # 515/462/1015		
Provide a copy of this report, the narrative report and sketch to the seller/agent, buyer/agent, the county sanitarian/environmental health office, county Recorder in the county the inspection was conducted and to;		
Iowa DNR Onsite Wastewater Program 502 E. 9 th St. Des Moines, IA 50319		

人を言せらに

The state of the s ITHERA LLED BY! POUBLE WIDE C& L CONST. Dany K. Joseph you 11/1/94 1 - 1000 GALLON DBL. COMP. LISTER SEPTIC TANK 43' +/- SCH 40 TO CLEAN-OUT 1 - TUP TITE PLASTIC DIST. BOX 4- 100 FT - 10 INCH GRAVELLESS LATERALS 1 -1 ήÇ, ¥7. ---5.80% SEPTIC TANK 1000 GALLON LISTER 1831+1-24" Chamber Lateral S PE NCE To replace 10" growelless 7/23/03 ZM A. Zet a. Rough ρ 000 PLASTIC TURTIFIED 100 GRAVELLESS GRAVELLESS GRAVELLESS 100' - 10" GRAVEL LESS . 1